

MJ 11-A

MJ11-A

THE FOLLOWING MODULES/ASSEMBLIES ARE CONTAINED IN THIS DEVICE.
EACH MAY HAVE ASSOCIATED TECH TIPS, DEC-O-LOG AND FCO's DOCUMENTED
IN THE MODULE/ASSEMBLY CATEGORY OF THE MICROFICHE LIBRARY

G114

G235

H217

H744

H745

M8148

M8149

54-11086

54-11553

54-11581

54-11583

70-06501

70-09769

70-10208

70-10214

70-10497

70-10498

70-10532

70-10580

70-10581

70-10694

70-10695

70-10780

70-10791

70-10824

70-10826

70-10974


70-10975

70-11027

70-11222

70-11223

**TECH.
TIPS**

	FIELD SERVICE TECHNICAL MANUAL				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	MJ11 MEMORY

Title MJ11-U/UP MEMORIES FAILING HIGH CURRENT MARGINS				Tech Tip Number	MJ11 TT-2
Processor Applicability		Author	Jim Holderby	Rev	g
All		Approval	Lee Mickle	Date	9-13-76
11/70					Cross Reference MJ11-TT-15

This Tech Tip is issued for cross reference purposes only.

Title INTERMITTENT PARITY ERRORS AND/OR SYSTEM SOFTWARE FAILURES				Tech Tip Number	MJ11 TT-3
Processor Applicability		Author	Jim Holderby	Rev	g
All		Approval	Lee Mickle	Date	9-15-76
11/70					Cross Reference

Intermittent parity errors and/or system software failures have been caused by the H873 memory bus terminator (in M8149 Rev. "A" board only) not seated in connector properly. ECO M8149-0004 corrects this problem. Therefore, if any of these systems occur and the M8149 module is an etch Rev. "A", install ECO M8149-0004 or swap this Rev. "A" module for a Rev. "C" module.

A quick check for this ECO is to see if the H873 terminator is secured to the M8149 by nylon screws.

Title MEMORY BUS CABLING				Tech Tip Number	MJ11-TT-4
Author		JIM HOLDERBY	F S Office	MAYNARD	Date
Processor Applicability					9-13 77
All		Mgr /Sup	LEE MICKLE	Date	9-13-77
1	1	/	7	0	
		Approval	LEE MICKLE	Date	9-13-77
					Cross Reference

THE MJ11 MAINTENANCE MANUAL AND THE 11/70 SYSTEMS INSTALLATION MANUAL ARE NOT VERY CLEAR ON THE INSTALLATION OF THE BC06-R MEMORY BUS CABLES. THESE CABLES SHOULD BE INSTALLED IN THE MJ11 BOX WITH THE RED STRIPE FACING THE FRONT OF THE MJ11 BOX. AT THE PROCESSOR, THE CABLES SHOULD BE INSTALLED WITH THE RED STRIPE FACING THE MODULE HANDLES.

FCR

MJ11
MEMORY TIMING AND CONTROL
FCO Cross Reference

A Chronological Listing of Field Retrofit FCO's Which Must Be
Considered in the Field Installation and Maintenance of This Option/Module/Power Supply

• Indicates FCO Conjunction Must Be Considered With Prior FCO

1 **M8148-S0003 OCT 76**
QUICK SYNOPSIS
Eliminates timing drift of READ TIMING
DELAY LINE DRIVER
QUICK CHECK
Wire between C94 and D2 (cathode)
NEW REVISION
Rework etch A to CS C

2 **M8149-S0004 JUL 76**
QUICK SYNOPSIS
Eliminates intermittent system software
failures
QUICK CHECK
Nylon screws hold H873 to M8149
NEW REVISION
Rework etch A to CS A1

3 **G235-S0009 SEP 76**
QUICK SYNOPSIS
Memory is marginal due to high drive current
QUICK CHECK
75 ohm resistor at + symbol near large etch
NEW REVISION
Rework etch D to CS N

4

MM11

THE FOLLOWING MODULE/ASSEMBLIES ARE CONTAINED IN THIS DEVICE. EACH MAY HAVE ASSOCIATED TECH TIPS,
DEC-O-LOG AND FCO's DOCUMENTED IN THE MODULE/ASSEMBLY CATEGORY OF THE MICROFICHE LIBRARY.

70-06468
70-07263
70-09562

G102
G103
G109
G110
G225
G226
G231
G615
G616
G645

H213
H214

M109
M229
M1091
M7290

TECH TIPS

FIELD SERVICE TECHNICAL MANUAL				Option or Designator MM11
12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	

Title QUALADYNE 1540 SENSE AMPS			Tech Tip MM11 Number 01
AN	Processor Applicability	Author DON ZERESKI Rev A	Cross Reference
		Approval CHUCK DEWEY Date 6/27/72	

The Qualadyne 1540 sense amps have had bonding problems. The unit is used in most current DEC sense amplifier boards. The Motorola 1540 should be used as its replacement when necessary. Most of the defective units have been replaced during production. These were used in MM11-E and F memories.

Since the Motorola 1540 units are in short supply, Production is only replacing failing units and are not retrofitting all boards in all product lines. Machines in the field that exhibit strange memory problems that can be localized to sense amp problems should be checked for Qualadyne units with the following date codes: 7014, 7016, 7020, 7022, 7024, 7031, and 7032. These units may be defective and should be replaced as a last resort. We are not suggesting a purge of all Qualadyne units of the above mentioned date codes or future Qualadyne units.

Title H207E MEMORY STACK			Tech Tip MM11 Number 02
AN	Processor Applicability	Author TOM KARPOMSKI Rev A	Cross Reference
		Approval CHUCK DEWEY Date 6/27/72	

The MM11-E memory will be using a new stack, RCA's H207E. This stack can only be used in an MM11-E. The H207 stack can be used in an MM11-E and MM11-F.

Title MM11-E & F/G102 MODULES			Tech Tip MM11 Number 03
AN	Processor Applicability	Author TOM KARPOMSKI Rev 0	Cross Reference
		Approval CHUCK DEWEY Date 6/1/72	

ECO G102-00005 has been written to make the G102 module capable of running in the MM11-F memory. This ECO makes this module CS revision D. It has to be at least revision D to run in an MM11-F. This revision can also be used in MM11-E's. Please see that your spares are modified accordingly.

Title INTERLEAVING THE MM11-E MEMORY			Tech Tip MM11 Number 04
AN	Processor Applicability	Author JOHN BUZYNSKI Rev 0	Cross Reference
		Approval CHUCK DEWEY Date 6/1/72	

Interleaving is simply addressing the memory such that adjacent memory banks are selected on alternate cycles. Thus, it is interleavable in 8K increments or blocks. This is implemented by interchanging BUS A01L and BUS A13L inputs to the memory between the bus inputs and memory device select and control. The memory being addressed, for example, in a DAT1 mode is free to complete its cycle after the MSYN L-SSYN1 dialog and as soon as the setup times for the bus are satisfied, MSYN L can be reasserted to

PAGE 1	PAGE REVISION A	PUBLICATION DATE June, 1972
--------	-----------------	-----------------------------

Title INTERLEAVING THE M11-E MEMORY (Continued)				Tech Tip M111 Number 04	
AN	Processor Applicability			Author JOHN BUZYNSKI	Rev 0
				Approval CHUCK DEWEY	Date 6/1/72
Cross Reference					

start a memory cycle in the adjacent memory bank while the first memory bank is completing its cycle. A significant increase in memory throughput occurs.

In the M11-E the two address bits have to be physically interchanged on the back-plane. It is also necessary to modify M729 control logic module to speed up the SSYML reset circuit. (Refer to ECO's M11-E Numbers 17, 19, and 20; M729 number 2; and ECO M1091 number 1).

Remember, when troubleshooting an interleaved memory, that successive addresses reference alternate memory banks.

Title FIELD INSTALLATION OF M11-E ON PDP-11/45				Tech Tip M111 Number 05	
AN	Processor Applicability			Author ANDY VEROSTIC	Rev 0
	11/45			Approval ART ZINS	Date 6/7/72
Cross Reference					

HARDWARE

Existing M729 control must have ECO #M729-00003 installed for operation on 11/45.

DIAGNOSTICS

All present memory tests will run on the 11/45.

Title FIELD INSTALLATION OF M11-F ON PDP-11/45				Tech Tip M111 Number 06	
AN	Processor Applicability			Author ANDY VEROSTIC	Rev A
	11/45			Approval ART ZINS	Date 6/7/72
Cross Reference					

HARDWARE

Existing M7290 control must have ECO's #M7290-00002 and 00003 installed for proper operation on the 11/45.

DIAGNOSTICS

All present memory tests run on the 11/45.


Title MM11-E and F MEMORY ADDRESS SELECTION AND INTERLEAVING		Tech Tip Number MM11-TT 87
AH	Processor Applicability	Author Chuck Dewey Rev 9
		Approval Chuck Dewey Date 9/28/72
		Cross Reference


Interleaving

Interleaving for MM11-E memories is described in Tech Tip MM11 number 4. It can only be accomplished by system unit wire changes to the back plane. Refer to the ECO's, listed in the Tech Tip, for proper implementation.


MM11-F interleaving is accomplished by manipulation of jumper wires on the M1091 module. These changes are shown in Table 1. It is a normal procedure for the production line to interleave all 8K segments of MM11-F memory on the initial system prior to shipment.

Interleaving of a MM11-E with an MM11-F is not recommended primarily due to the confusion it creates in troubleshooting a system of this nature. It also creates customer misunderstanding since the average memory cycle time specification, in this situation, would not be either the MM11-E or F but somewhere in between.



	FIELD SERVICE TECHNICAL MANUAL				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	MM11

Title		Tech Tip	
MM11-E and F MEMORY ADDRESS SELECTION & INTERLEAVING (CONT'D)		MM11-TT	
Number		07	
Processor Applicability	Author	Rev	Cross Reference
All	Chuck Dewey	1	
	Approval	Date	
	Chuck Dewey	9/28/72	



THIS DOCUMENT WAS NOT PRODUCED FOR MICROFICHE, THEREFORE, ONLY PARTS OF IT ARE READABLE.

Title MM11-E and F MEMORY ADDRESS SELECTION & INTERLEAVING (CONT'D)				Tech Tip MM11-TT	
All Processor Applicability				Number 07	
Author Chuck Dewey		Rev #		Cross Reference	
Approval Chuck Dewey		Date 9/28/72			


TABLE 1

Bank	K WORDS	ADDRESSES		NON-INTERLEAVED MM11-F AND ALL MM11-E MEMORIES								INTERLEAVED MM11-F MEMORY *							
		FROM	TO	17		16		15		14		13		01		13		01	
				I	O	I	O	I	O	I	O	A	B	C	D	A	B	C	D
1	0-4	00000	017776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
2	4-8	02000	037776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
3	8-12	04000	057776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
4	12-16	06000	077776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
5	16-20	10000	117776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
6	20-24	12000	137776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
7	24-28	14000	157776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
FROM THIS POINT ON A DEVICE SUCH AS MX11, KS11, OR KT11 IS REQUIRED																			
8	28-32	16000	177776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
9	32-36	20000	217776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
10	36-40	22000	237776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
11	40-44	24000	257776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
12	44-48	26000	277776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
13	48-52	30000	317776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
14	52-56	32000	337776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
15	56-60	34000	357776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
16	60-64	36000	377776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
17	64-68	40000	417776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
18	68-72	42000	437776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
19	72-76	44000	457776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
20	76-80	46000	477776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
21	80-84	50000	517776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
22	84-88	52000	537776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
DE11 REQUIRED FROM THIS POINT IF DE11 IS IN USE																			
23	88-92	54000	557776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
24	92-96	56000	577776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
25	96-100	60000	617776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
26	100-104	62000	637776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
27	104-108	64000	657776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
28	108-112	66000	677776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
29	112-116	70000	717776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
30	116-120	72000	737776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
31	120-124	74000	757776	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	

S/S ADDRESSING BEYOND THIS POINT - RESERVED FOR DEVICES

X DENOTES JUMPER INSERTION ON THE BOARD AT THE IDENTIFIED POINT

* INTERLEAVING CAN ONLY BE ACCOMPLISHED WITH 8K SEGMENTS OF MEMORY. THE XXXXX0 AND XXXXX4 ADDRESSES ARE TO BE ASSIGNED TO ODD BANK MEMORIES

	FIELD SERVICE TECHNICAL MANUAL				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	

Title DATA ERRORS CAUSED BY D.C.L.O OR INIT ON MM11-K, L, M, S				Tech Tip Number 4811 #8
Processor Applicability		Author A Verostic/D. Dickhut	Rev g	Cross Reference
AN		Approval Art Zins	Date 1/27/72	

Problem exist with the 4K-8K PDP-11 memory (MM11-S, M11, MM11-L) that appear to be hardware data errors, but disappears if every word in memory is accessed. The problem usually occur when ever Initialize or D.C.L.O occurs during a memory cycle. This turns off the current drivers at the wrong time, leaving some cores in a partially switched state. Half-selected cores contribute large amounts of noise when accessing other words, causing intermittent failures.

Errors occurring during a memory cycle can be eliminated if the power fail trap is used properly. The power fail trap sequence should turn off any peripheral that might access memory (individually, not by using INIT) and halt the processor before D.C.L.O occurs.

The chances of INIT occurring during a memory cycle will be reduced if software avoids using the RESET instruction, particularly inside tight loops. The condition of half selected cores can be cured by accessing every word in memory to assure all cores are fully switched. Once this is completed, data may be read and written normally.

Title MM11-K, L, M, and S Field Problem Summary		Tech Tip Number MM 11 TT-9	
AN	Processor Applicability	Author D. Dickhut	Rev p
		Approval C. Dewey	Date 11/20/72
Cross Reference			

This Tech Tip is a summary of field problems and their solutions for the MM11-K, L, M, and S memories which are found in MM11 which uses only MM11-L, 11/05 and 11/10 which use MM11-R (4K 11/05 only and MM11-L (8K, 11/40 which uses only MM11-L (8K), and 11/45 which uses only MM11-L (8K).

1. Random Memory Locations are Altered during Power Fail

The contents may be altered while running Power Fail Diagnostic or by simply turning the machine on and off. ECO G231-5 solves this problem.

2. Memories do not have to be swapped as a system all 3 modules


A system that is shipped has a serial number stamped on side 2 of each module. This number is the same on all 3 modules and is strictly for in-house test purposes only. The memories can be and should be maintained on a module swap basis instead of a system basis (stack not used anyway). The system serial number can be used in a case where such swapping has taken place and now the modules are to be put back in their original configuration. By matching the serial number, each system can be reunited and a lot of adjustment time can be saved.

3. What adjustments to make when a module is swapped.

When anyone of the 3 modules that make up the memory system is swapped, the strobe adjustment must be made to ensure system reliability (When the G110 module is swapped, it has the strobe pot but the setting cannot be taken for granted). The procedure to use for strobe adjustment is as follows:

1. If strobe adjustment is too far off, EXAM and DEP may not work. To get strobe in the ballpark, sync on pin CU2 of the G110 model (signal READ H) and Test Point 5 of E05 pin 9 for strobe. Press EXAM rapidly and adjust strobe using pot on G110 for a 250 ns delay from rising edge of READ H to rising edge of strobe. This should allow diagnostics to be read in.
2. Load Worst Case Noise Diagnostic (W.C.N. should be used not a Branch ... F)
3. Load Address 200 and START or Load Address 202 to select the desired bank.
4. Sync on pin CU2 of G110 (signal READ H) while scoping Test Point 5 or E05 pin 9 for strobe and margin strobe by turning pot CW until the diagnostic fails and then CCW until it fails. A complete pass of the diagnostic should be made (within reasonable limits for large core systems) at each high and low end point to ensure that is the true end point. Notice the time from the leading edge of READ H to strobe in each case. The total strobe window should be 40 ns or greater and set strobe in the middle of the high and low points. If the window isn't at least 40 ns, then the entire system should be changed because margin problems can only be dealt with back at Module Repair Depot.

This procedure is graphically illustrated and explained in the MM11-K, MM11-L, 11/05, and 11/40 manuals.

	FIELD SERVICE TECHNICAL MANUAL				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	MM 11

Title MM11-K, L, M, and S Field Problem Summary				Tech Tip Number	
Author				Rev	
Approval				Date	
AM	Processor Applicability			Cross Reference	

4. UIC memory stack threshold problem

Some DEC or RCA memory stacks (L stack identified by label on side) some may have RCA stickers have a threshold problem and will not exhibit the normal threshold margin. In order to use these previously rejected stacks in production, the sense circuitry on the G110 was modified. In the field, if a memory stack is swapped and it is a DEC stack, the UIC module should be checked to see if EC 06 is installed. If it isn't and this is a non-field effect EC 06 module with that EC should be obtained from the Maynard Module Repair Dept. The new UIC stack may or may not have this problem and probably will operate properly even if it does. However, with large systems or several NIM (LMA) devices, intermittent failures may occur over a long period of time.

Title: 11-17 MODIFICATION FOR THE G110, G111K and G111L NEW KIT				Tech Tip Number: 11-10	
Processor Applicability: All		Author: G. Gallo		Rev: 0	
		Approval: C. Dewey		Date: 12/12/72	
Cross Reference					

The following Tech Tip will attempt to clarify the confusion regarding the ECO status for the G110, G111K and G111L memories.

1. Background

In the near future there will be two separate types of G110 Modules in the field. The first type of G110 Module is an Etch Revision C Module which already exists in the field. The second type of module will be an Etch Revision E.

It will not be possible to ECO the Etch Revision C Module so that it will be electrically equal to the Etch Revision E Module. For this reason it has become necessary to create two separate sets of engineering drawings to cover the two different modules.


The engineering drawings for the Etch Revision C Module will have a circuit schematic revision of 1 with one numeric digit following. Each ECO released will increment the numeric digit by one (i.e. F1, F2, F3, and so on).

The engineering drawings for the Etch Revision E Module will have a circuit schematic revision of 1 with an alpha character starting at F and continuing sequentially (i.e. F, H, J, L, and so on).

Table 1 is a list that shows the revisions for the two G110 Modules.

G110 Etch Revision C		G110 Etch Revision E	
Part No.	Revision	ECO No.	Revision
G110-001	A	G110-001	F
G110-002	I	G110-001	H
G110-004	F A		
G110-005	F A		
G110-006	F		
G110-007	F-1		
G110-008	F-2		
G110-009	F-3		
G110-010	F-4		
G110-012	F-5		

Note: There have been a number of Etch Revision E Modules shipped that were marked Rev H and J. These should have been marked Rev E3 and E4 respectively.

	FIELD SERVICE TECHNICAL MANUAL				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	MM11

Title ECO DOCUMENTATION FOR THE MM11K, MM11L and MM11S Memories (Continued)				Tech Tip Number MM11-TT-10	
Processor Applicability		Author G. Cable	Rev g	Cross Reference	
AH x		Approval C. Dewey	Date 12/12/72		

G231 Module

There will also be two separate types of G231 Modules in the field in the near future. For this reason it has become necessary to create two sets of engineering drawings.

The first type of G231 Module will be an Etch Revision of C. All future ECO's for this module will use a circuit schematic revision of E with a numeric digit following. Each ECO released will increment the numeric digit by one (i.e. E4, E5, E6 and etc.).

The second type of G231 Module will be an Etch Revision of E. All future ECO's for this module will use a circuit schematic revision with only an alpha character as a designator starting at CS Revision F and incrementing thru the alphabet (i.e. F, H, J, K, and etc.).

Below is a chart that shows the revisions for the two G231 Modules.

G231 Etch Revision C			G231 Etch Revision E	
ECO No.	CS Revision	Stamped on Module	ECO No.	CS Revision
G231-0001	C	C	G231-0004	F
G231-0002	N/A	N/P		
G231-0003	C-1	E		
G231-0005	1	E-1		
G231-0006	2	E-2		
G231-0007	3	J		
G231-0008	3A	3A		
G231-0009	E4	E4		

Refer to PDP 11/05 Systems Tech Tip #14 for a detailed listing and description of memory ECO's.

m3

Title				Tech Tip	
New MM11 Option Designations				Number	
				MM11-TT-11	
Processor Applicability		Author	Rev	Cross Reference	
All		D. Duckbus	1		
		Approval (Dewey)	Date		
			1/19/73		

This tech tip is to define the new variations of memories that are in existence and how they differ from the present MM11-L and S memories. The MM11-L and S are defined again for reference.

MM11-L (8K X 16, 900 ns)

It consists of a G110, G231 and H214 and is used on 11/05, 11/10, ME11-L and 11/40.

MM11-S (8K X 16, 900 ns)

This consists of a G110, G231, H214, and a system unit. It is used on 11/35, 11/40 to 11/45.

MM11-LP (8K X 16, memory parity)

This consists of a G109, G231 and H215 and is designed for memory parity. It plugs into a MF11-LP.

MF11-IP (Parity Option)

This is a memory parity option that consists of a nine slot backplane, one MM11-L and one M7259 double height double width memory parity controller. The backplane can accommodate three MM11-LP's. This option is used on 11/35, 11/40 and 11/45.

MF11-L

This is a memory option that consists of a nine slot backplane and one MM11-L. It can accommodate three MM11-L and is used on 11/35, 11/40 and 11/45.


MB11-S (8K X 16)

This is a special 8K X 16 memory with a 850 ns cycle time and consists of a G110-YA, G231, and H214-YA. This memory is used only on 11/45 and exists in very limited quantities.

G109-YA (for reference only)

Module used only on PDP15 memories.

It is important to remember that the modules mentioned in the above definitions are not interchangeable with a similar looking type in another category. For example a G109 is not interchangeable with a G110 nor is a G110 interchangeable with a G110-YA. When a memory module is replaced or swapped, it should only be replaced with the exact same module type, even though another type may appear to work.

	FIELD SERVICE TECHNICAL MANUAL				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	MM 11

Title MM11- E and F in BALL-B/D/F Mounting Boxes				Tech Tip Number MM11-TT-12	
All	Processor Applicability		Author B. Dimbat	Rev 0	Cross Reference
			Approval C. Dewey	Date 3/14/73	


MM11E and MM11F memories cannot be installed in the 11/40 box. They cannot be installed in BALL-B/D/F boxes. They can be used on the 11/40 system but only if they are installed in an 11/20 type box (BALL-ES), which has its own power supply.

MM11E/F's, installed in an 11/40 box, will lose data during the power down sequence.

21

Title MM11 L, S, K Memory Address Decode				Tech Tip Number MM TT 13	
All	Processor Applicability		Author John Alston	Rev g	Cross Reference
			Approval B. Dimbat	Date 6/1/73	

The diagram and tables supplied here are to aid F/S men when they are troubleshooting MM11L, S & K memories by relating the drive signals on the G231 with the addresses that generate them.



cy

	FIELD SERVICE TECHNICAL MANUAL				Option or Designator
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	MM11

Title MM11 I, S, K Memory Address Decode				Tech Tip Number MM11-TT-13	
All Processor Applicability		Author J. Alston	Rev 0	Cross Reference	
		Approval B. Dimbat	Date 6/1/73		

	A11=1, A10=1	A11=1, A10=0	A11=0, A10=1	A10=0, A11=0
A13=1 A12=1	XS15	XS14	XS13	XS12
	E40			
A13=1 A12=0	XS11	XS10	XS09	XS08
	E37			
A13=0 A12=1	XS07	XS06	XS05	XS04
	E34			
A13=0 A12=0	XS03	XS02	XS01	XS00
	E31			

TABLE A

	A08=1, A07=1	A08=1, A07=0	A08=0, A07=1	A08=0, A07=0
Read A09=1	XFRD7	XFRD6	XFRD5	XFRD4
	E46			
Read A09=0	XFRD3	XFRD2	XFRD1	XFRD0
	E43			
Write A09=1	XNWD7	XNWD6	XNWD5	XNWD4
	E46			
Write A09=0	XNWD3	XNWD2	XNWD1	XNWD0
	E43			

TABLE B

D4

Title MM11, L, S, K Memory Address Decode			Tech Tip Number MM TT 13	
All	Processor Applicability		Author J. Alston	Rev g
			Approval E. Dimbat	Date 6/1/73
Cross Reference				

TABLE C

	A05=1, A04=1	A05=1, A04=0	A05=0, A04=1	A05=0, A04=0
A06=1	YS07	YS06	YS05	YS04
	E28			
A06=0	YS03	YS02	YS01	YS00
	F23			

TABLE D

		A02=1, A01=1	A02=1, A01=0	A02=0, A01=1	A02=0, A01=0
read	A03=1	YPRD7	YPRD6	YPRD5	YPRD4
		E8			
	A03=0	YPRD3	YPRD2	YPRD1	YPRD0
		E3			
write	A03=1	YNWD7	YNWD6	YNWD5	YNWD4
		E8			
	A03=0	YNWD3	YNWD2	YNWD1	YNWD0
		E3			

FIELD SERVICE TECHNICAL MANUAL				Option or Designator MM11
12 Bk <input type="checkbox"/>	16 Bk <input checked="" type="checkbox"/>	18 Bk <input type="checkbox"/>	36 Bk <input type="checkbox"/>	MEMORY OPTIONS

Title MM11-D/DP Memory Backplane			Tech Tip Number MM11-TT-14	
Processor Applicability All		Author William Aupperle	Rev g	Cross Reference
		Approval William Dimbar	Date 8-5-76	

The MM11-D/DP Core Memory Manual states that the G652 (mother board for the MM11-D/DP) is inserted into a "Unibus Backplane". To eliminate any confusion, the "Unibus Backplane" is the modified backplanes DD11-C, D and P used on 11/04, 11/34 systems. Other Unibus Backplanes, such as 11/05, 11/35 and DD-11B expansion backplanes are not compatible with these new memory boards.


Title MM11-U/UP MEMORIES FAILING HIGH CURRENT MARGINS			Tech Tip Number MM11-TT-15	
Processor Applicability All		Author Jim Holderby	Rev g	Cross Reference
		Approval Lee Mickle	Date 9-13-76	

Many reports have been received from the field concerning memories failing high current margins and module set incompatibility (i.e. unable to swap modules). Investigation has shown that the inhibit margins are not properly centered, which could cause marginal operation of the memory under conditions of high drive currents. An ECO (G235-0009) was generated to correct this problem.

Therefore, if a memory exhibits these symptoms, do a visual inspection of the G235 for the ECO. A quick check for the ECO is:

1. Place G235 component side up and fingers toward you.
2. Look at right hand side of module in large etch area (see drawing).
3. If resistor R103 (750 1W) which is across bottom of large etch is not in, ECO has not been installed.

This ECO should be installed before attempting massive module swap or option swap.



Title MM11-U/UP INSTALLATION					Tech Tip Number MM11 TT-16	
Processor Applicability			Author Jim Holderby		Rev g	
All			Approval Lee Mickle (jm)		Date 12-14-76	
X					Cross Reference	

There is a problem if more than 64K of MM11-U memory is installed in the new type expansion box (RALLF) with power distribution harness 7009566. When the second H754 power supply is installed, the jumpers must be removed from the power harness. The jumpers connect P2 pin 3 to P5 pin 3 and P2 pin 14 to P5 pin 14. If these jumpers are not removed, the two(2) H754 power supplies are connected in parallel and it is possible to damage one or both regulators. The reason the jumpers are there is to allow us to install the memory backplane anywhere in the cabinet.

This information is not in the installation procedure; however, it can be found in the PDP 11/45 and 11/50 System Maintenance Manual (DEC-11-H45SM-D-D) Figure 8-5, power distribution schematic.

Title MM11-E TROUBLE SHOOTING AID					Tech Tip Number MM11-TT-17	
Author MICHAEL BABCOCK			FS Office PITTSBURGH, PA		Date 7 JUNE 77	
Processor Applicability			Mjr /Sup		Date	
All			Approval JIM HOLDERBY		Date 15 JUN 77	
					Revision 0	
					Cross Reference	


THE FOLLOWING IS INTENDED AS A TROUBLE SHOOTING AID FOR THE MM11-E MEMORY

MEMORY SELECT		ADDRESS													
		X SWITCH READ AND WRITE			X DRIVER READ AND WRITE			Y SWITCH READ AND WRITE			Y DRIVER READ AND WRITE				
15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
			$\phi_{(0)} = X50$			$\phi_{(0)} = XD0$			$\phi_{(0)} = Y50$			$\phi_{(0)} = YD0$	BYTE SELECTION		
			$1_{(0)} = X51$			$1_{(0)} = XD1$			$1_{(0)} = Y51$			$1_{(0)} = YD1$			
			$2_{(0)} = X52$			$2_{(0)} = XD2$			$2_{(0)} = Y52$			$2_{(0)} = YD2$			
			$3_{(0)} = X53$			$3_{(0)} = XD3$			$3_{(0)} = Y53$			$3_{(0)} = YD3$			
			$4_{(0)} = X54$			$4_{(0)} = XD4$			$4_{(0)} = Y54$			$4_{(0)} = YD4$			
			$5_{(0)} = X55$			$5_{(0)} = XD5$			$5_{(0)} = Y55$			$5_{(0)} = YD5$			
			$6_{(0)} = X56$			$6_{(0)} = XD6$			$6_{(0)} = Y56$			$6_{(0)} = YD6$			
			$7_{(0)} = X57$			$7_{(0)} = XD7$			$7_{(0)} = Y57$			$7_{(0)} = YD7$			

X AND Y DRIVER SIGNALS ARE POSITIVE FOR READ; NEGATIVE FOR WRITE
(i.e. YPD ϕ FOR READ; YND ϕ FOR WRITE)

X AND Y SWITCH SIGNALS ARE NEGATIVE FOR READ; POSITIVE FOR WRITE
(i.e. XNS ϕ FOR READ; XPS ϕ FOR WRITE)

YD ϕ - YD3 ON G226 SLOT C03	XD ϕ - XD3 ON G226 SLOT C02
YD4 - YD7 ON G226 SLOT F03	XD4 - XD7 ON G226 SLOT F02
YS ϕ - YS3 ON G226 SLOT C03	XS ϕ - XS3 ON G226 SLOT C02
YS4 - YS7 ON G226 SLOT F03	XS4 - XS7 ON G226 SLOT F02

	FIELD SERVICE TECHNICAL MANUAL				Option or Designator MM11
	12 Bit <input type="checkbox"/>	16 Bit <input checked="" type="checkbox"/>	18 Bit <input type="checkbox"/>	36 Bit <input type="checkbox"/>	MEMORY OPTION

Title MM11-E TROUBLE SHOOTING AID (CONT)		Tech Tip Number MM11-TT-17	
Author MICHAEL BABCOCK	FS Office PITTSBURGH, Pa	Date 6/17/77	Revision 0
Processor Applicability		Mgr /Sup	Date
All 11		Approval JIM HOLDERBY	Date 6/17/77
		Cross Reference	

LOSS OF A BYTE - TROUBLE WITH BIT 0
LOSS OF 1 (OCTAL) IN EVERY 20 (OCTAL) LOCATIONS - BAD Y DRIVER
LOSS OF 20 (OCTAL) LOCATIONS IN EVERY 200 (OCTAL) LOCATIONS - BAD Y SWITCH
LOSS OF 200 (OCTAL) LOCATIONS IN EVERY 2,000 (OCTAL) LOCATIONS - BAD X DRIVER
LOSS OF 2000 (OCTAL) LOCATIONS IN EVERY 20000 (4K) (OCTAL) LOCATIONS - BAD X SWITCH

ANY DATA BIT DROPAGE OR PICKUP IS PROBABLY CAUSED BY THE G102'S

DATA BITS 0-3	G102 SLOT D03
DATA BITS 4-7	G102 SLOT D02
DATA BITS 8-11	G102 SLOT E03
DATA BITS 12-15	G102 SLOT E02

ADDRESS BIT 0 - BYTE SELECT DURING DATOB

ADDRESS BITS 1-3			READ DRIVER	WRITE DRIVER	
3	2	1			
0	0	0	YPD0	YND0	
0	0	1	YPD1	YND1	SWITCH/DECODER A
0	1	0	YPD2	YND2	G226 SLOT C03
0	1	1	YPD3	YND3	
1	0	0	YPD4	YND4	
1	0	1	YPD5	YND5	SWITCH/DECODER B
1	1	0	YPD6	YND6	G226 SLOT F03
1	1	1	YPD7	YND7	

ADDRESS BITS 4-6					
6	5	4			
0	0	0	YNS0	YPS0	
0	0	1	YNS1	YPS1	SWITCH/DECODER C
0	1	0	YNS2	YPS2	G226 SLOT C03
0	1	1	YNS3	YPS3	
1	0	0	YNS4	YPS4	
1	0	1	YNS5	YPS5	SWITCH/DECODER D
1	1	0	YNS6	YPS6	G226 SLOT F03
1	1	1	YNS7	YPS7	

DEC CONFIDENTIAL
This document is proprietary to Digital Equipment Corporation and is intended for use by its Field Service Organization only
For information on writing or approving a Tech Tip, see Administration Tech Tip Number 2

Page 19	Page Revision 0	Publication Date JUNE 1977
---------	-----------------	----------------------------

PRINTED IN U.S.A.

HY

Title MM11-E TROUBLE SHOOTING AID (CONT)				Tech Tip Number MM11-TT-17	
Author MICHAEL BABCOCK		F S Office PITTS., PA		Date 6/17/77	Revision 0
Processor Applicability		Mgr /Sup		Date	Cross Reference
All	11	Approval JIM HOLDERBY		Date 6/17/77	

ADDRESS BITS 7-9

9	8	7			
0	0	0	XPD0	XND0	
0	0	1	XPD1	XND1	SWITCH/DECODER A
0	1	0	XPD2	XND2	G226 SLOT C02
0	1	1	XPD3	XND3	
1	0	0	XPD4	XND4	
1	0	1	XPD5	XND5	SWITCH/DECODER B
1	1	0	XPD6	XND6	G226 SLOT F02
1	1	1	XPD7	XND7	

ADDRESS BITS 10-12

12	11	10			
0	0	0	XNS0	XPS0	
0	0	1	XNS1	XPS1	SWITCH/DECODER C
0	1	0	XNS2	XPS2	G226 SLOT C02
0	1	1	XNS3	XPS3	
1	0	0	XNS4	XPS4	
1	0	1	XNS5	XPS5	SWITCH/DECODER D
1	1	0	XNS6	XPS6	G226 SLOT F02
1	1	1	XNS7	XPS7	

Title M7850 S SYN DLY ADJUSTMENT (MM11-CP, MM11-DP)				Tech Tip Number MM11-TT-18	
Author JIM HOLDERBY		F S Office MAYNARD		Date 9-23-77	Revision 0
Processor Applicability		Mgr /Sup LEE MICKLE		Date 9-23-77	Cross Reference
All		Approval LEE MICKLE		Date 9-23-77	M7850-TT-1


THIS TECH TIP APPLIES TO MM11-CP AND MM11 DD. CROSS REFERENCE M7850.

14

MM11-E

MM11-E/F PARTS BREAKDOWN

7006405	- Logic Frame
7006468	- MM11-E Wired assembly
70007263	- MM11-F Wired assembly
G102	- Sense Inhibit Card
G103	- Memory Levels & Gates
G225	- X-Y Current Generator
G226	- X-Y Current Generator
H207	- 4K 16 Bit Core Memory Stack
M109	- Device Select
M729	- MM11-E Control Logic
M1091	- Device Select
M7290	- Control Logic & Timing
MM11-E	- 4K Single Memory Unit
MM11-EX	- 4K Interleaved
MM11-F	- 4K Single Memory Unit
MM11-FP	- Single Parity Memory Unit
MM11-FX	- Interleaved Memory (jumpers)



THIS DOCUMENT WAS NOT PRODUCED FOR MICROFICHE; THEREFORE, ONLY PARTS OF IT ARE READABLE.

Engineering Change Order Log

ECO SYNOPSIS pages are updated and published continuously in conjunction with the issuance of ENGINEERING CHANGE ORDERS for all DEC products and are available upon subscription from:

DIGITAL EQUIPMENT CORPORATION
FIELD SERVICE INFORMATION CENTER
MAYNARD MASSACHUSETTS 01704

DIGITAL EQUIPMENT CORPORATION
MAYNARD MASSACHUSETTS

ECO SYNOPSIS FOR LOGIC OR OPTION

PDP-11 MEMORY **MMII-E**

PRODUCT LINE	PUBLICATION DATE OF THIS SYNOPSIS PAGE	PAGE REVISION
PDP-11	JULY 1976	8

ECO NO	LOGIC OR OPTION SERIAL NO'S AFFECTED	FIELD CODE	SYNOPSIS
MMII-E 0001	MMII-E	M	JAN 76 - CHANGES STACK HINGE TOLERANCE AND ADDS A FLATNESS SPECIFICATION.
MMII-E 0002	MMII-E 110-120	D	JAN 76 - MAKES CORRECTIONS TO THE WIRE LIST.
MMII-E 0003	MMII-E 110-120	D	JAN 76 - ADDS CURRENT LOOPS FOR X AND Y CURRENT MEASUREMENTS AND SCOPING. UPDATES THE LIST OF MANUALLY INSTALLED WIRING.
MMII-E 0004	MMII-E	D	JAN 76 - UPDATES THE MMII-E PRINT SET.
MMII-E 0005	N.A.	D	JAN 76 - CORRECTS A DRAWING WHICH WAS DRAWN IN REVERSE. ADDS CLARIFICATION NOTES.
MMII-E 0006	MMII-E 110-239	D	FEB 76 - ADDS TWO WIRES WHICH WERE PREVIOUSLY OMITTED FROM THE WIRE LIST.
MMII-E 0007	MMII-E	M	FEB 76 - CHANGES THE SPECIFICATION FOR THE MEMORY HINGE. SPECIFIES THE USE OF SELF EXTINGUISHING PLASTIC FOR MMII-E FABRICATION.
M729 0001	ALL M729	D	MAR 76 - REVISES SEVERAL DESIGN CONSIDERATIONS; CHANGES THE ET. LAYOUT AND SEVERAL COMPONENTS. MODULE STATUS - UNRELEASED. M729 CIRCUIT SCHEMATIC REVISION A ETCHED BOARD REVISION D
6226 0003	6226	D	MAR 76 - ADDS DIODES TO CLAMP OUTPUT VOLTAGE SPIES WHICH EXCEEDED THE TRANSISTOR BREAKDOWN RATING. MODULE STATUS - UNRELEASED. 6226 CIRCUIT SCHEMATIC REVISION C

LEGEND

FIELD CODE

F - Field or factory use only
D - Design
P - Part or sub-assembly change
M - Mechanical ECO

SYMBOLS

* - ECO applicable to future production

ECO CHARACTERS

Changes are coded within the synopsis: "S" "M" "M" "M"
S - Change for form and content only
M - Change for mechanical parts only
M - Change for electrical parts only
M - Change for software only
NOTE: Changes are coded as S, M, or M. Changes are coded for ECO retention by DEC.

MASTER DRAWING LIST REVISIONS

REV	ECO NUMBER	REV	ECO NUMBER
A	MMII-E-0001		
B	MMII-E-0002		
C	MMII-E-0003		
D	MMII-E-0004		
E	MMII-E-0005		
F	MMII-E-0006		
	PDP11-0004		

WIRE LIST REVISIONS

REV	ECO NUMBER	REV	ECO NUMBER
A	MMII-E-0001		
B	MMII-E-0002		
	MMII-E-0006		

ECO NO	LOGIC OR OPTION SERIAL NO'S AFFECTED	FIELD CODE	SYNOPSIS
6107 0002	PDP-11	F	MAR 76 - REPLACES THE 6801 IC WITH A 74011 TO INCREASE SPEED. THIS MODULE CANNOT BE REWORKED IN THE FIELD. (ERRATA CORRECTED BY ECO 6107-0003) 6107 CIRCUIT SCHEMATIC REVISION D ETCHED BOARD REVISION D
6103 0002	ALL PDP-11	F	MAR 76 - REPLACES 547401N IC WITH 547401N TO INCREASE SYSTEM SPEED. THE MODULE CANNOT BE REWORKED IN THE FIELD. 6103 CIRCUIT SCHEMATIC REVISION D
6102 0003	PDP-11	F	APR 76 - CORRECTS AN ERROR IN ECO 6102-0002; CHANGES 100 OHM RESISTORS TO 75 OHMS. 6102 CIRCUIT SCHEMATIC REVISION D ETCHED BOARD REVISION D
MMII-E 2000	MMII-E	P	APR 76 - CORRECTS DIMENSIONS ON THE ETCHED BOARD DRAWING TO MEET STANDARDS.
MMII-E 2000	N.A.	P	APR 76 - CHANGES WIRING AND TUBING REFERENCES ON THE PARTS LIST.
6101 0004	ALL PDP-11	F	APR 76 - CHANGES M17 FROM A 100 OHM INPUT TO A 500 OHM INPUT. 6101 CIRCUIT SCHEMATIC REVISION C
610 0000	N.A.	D	APR 76 - DELETES THE MODULE HANDLE FROM THE 6616 PARTS LIST AND ADDS IT TO THE MEMORY STACK PARTS LIST. 6616 CIRCUIT SCHEMATIC REVISION D
6616 0000	6616	J	MAY 76 - INTERCHANGES THE POSITIONS OF THERMISTOR M11 AND RESISTOR M1. 6616 CIRCUIT SCHEMATIC REVISION
MMII-E 0010	N.A.	P	MAY 76 - ADDS A MODULE CLIP WITH PART NUMBER AND ITS DESCRIPTION TO THE PARTS LIST.
MMII-E 0011	MMII-E	P	MAY 76 - ADDS MMII-E ALIGNMENT PROCEDURE TO THE PRINT SET.
MMII-E 0012	MMII-E	J	MAY 76 - CHANGES A HOLE SIZE AND ADDS TWO DIMENSIONS FOR THE 6616.

LEGEND

F - Field or factory use only
D - Design
P - Part or sub-assembly change
M - Mechanical ECO

SYMBOLS

* - ECO applicable to future production

ECO CHARACTERS


Changes are coded within the synopsis: "S" "M" "M" "M"
S - Change for form and content only
M - Change for mechanical parts only
M - Change for electrical parts only
M - Change for software only
NOTE: Changes are coded as S, M, or M. Changes are coded for ECO retention by DEC.

MASTER DRAWING LIST REVISIONS

REV	ECO NUMBER	REV	ECO NUMBER
A	MMII-E-0001		
B	MMII-E-0002		
C	MMII-E-0003		
D	MMII-E-0004		

WIRE LIST REVISIONS

REV	ECO NUMBER	REV	ECO NUMBER
A	MMII-E-0001		
B	MMII-E-0002		
	MMII-E-0006		



FS

EQUIPMENT CORPORATION ENGINEERING CHANGE ORDER

REV. BY	REV. NO.	DATE	BY
	8	10	70
TYPE OF CHANGE			
ELECTRICAL			<input checked="" type="checkbox"/>
MECHANICAL			<input type="checkbox"/>
MODULES			<input type="checkbox"/>

CHANGE NO. M11B-00015
DOCUMENTATION PROJECT NUMBER
ASST. PROD. LINE TYPE OR DISCRETE NO.
2 2 0 7 4 2 8
MANUFACTURING PROJECT NUMBER
ASST. PROD. LINE TYPE OR DISCRETE NO.

UNIT NAME MEMORY MODEL NO. M11B

PREPARED SYSTEMS AFFECTED

MODEL NO.	VARIATION

CHANGE TESTED BY _____
ESTIMATED TIME TO INSTALL 4 MINUTES

PARTS ORDER TO BE MADE BY THE SHOP TO REPLACE ORDER

SHOP MODEL APPROVED	YES	NO
SYSTEMS PROGRAMS AFFECTED	<input type="checkbox"/>	<input checked="" type="checkbox"/>
DIAGNOSTIC PROGRAMS AFFECTED	<input type="checkbox"/>	<input checked="" type="checkbox"/>
TECHNICAL PUBLICATIONS AFFECTED	<input type="checkbox"/>	<input checked="" type="checkbox"/>

BREAK-IN POINT (DATE/GENERAL NO.)
FIELD RETROFIT ON MULTIPLE BOX SYS. ONLY. PHASE-IN PRODUCTION-- ALL MULTIPLE BOX SYS. FOR THE MONTH OF AUG. ALL MACHINES AS OF AUGUST 24, 1970.
P.R. #100-058

PROBLEM:

TO ALLOW PROPER POWER FAIL OF MULTIPLE BOX SYSTEMS.

- SIGNAL BUS AC LO L MUST BE CONNECTED FROM THE POWER BUS TO THE UNIBUS.
- SIGNAL BUS DC LO L MUST BE CONNECTED FROM THE POWER BUS TO THE UNIBUS.
- THIS ECO REQUIRES BOTH OF THE FOLLOWING: ECO #5408475-00006; ECO #M930-00001.

ALL REFERENCED CHANGES MUST BE MADE SIMULTANEOUSLY IN A GIVEN SYSTEM.

CORRECTION:

- INSTALL WIRES.
- CORRECT PRINTS.
- NOTE: IF INSTALLATION OF THIS UNIT CREATES A MULTIPLE BOX SYSTEM, THIS ECO AND ECO NUMBER 5408475-00006; ECO NUMBER M930-00001 MUST BE INSTALLED. ONE SET OF CONNECTIONS BETWEEN THE POWER BUS AND UNIBUS ARE REQUIRED FOR EACH BALL WITHIN A SYSTEM.

DRAWINGS AFFECTED

NUMBER	REV.
A-M-M11-B	1
B-M-M11-B-07	1
B-TC-M11-B-09	1

FIELD SERVICE CODES

F

ORIGINATOR Richard V. Manion DATE 8-3-70

PRODUCTION ENG. D. Call DATE 8-3-70

DESIGN ENG. Peter Durant DATE 8-3-70

OTHER R. J. Farrier AGK DATE 8-3-70

PRODUCT LINES AFFECTED

PDP-11

ADD/DELETE SHEET

MAKE ALL DELETIONS FIRST

PAGE _____ OF _____

COLOR	SIGNAL NAME	FROM PIN	TO PIN	COMPONENTS	ADD	DEL
	BUS ACL0L	B04F1	A03R2		X	
	BUS DCL0L	B04F2	A03S2		X	

ECO NUMBER MM11E-00015

MADE BY J. [Signature]


DRAWING NUMBER AFFECTED			
CODE	SIZE	NUMBER	REV LIT.
116	K	MM11-E-07	C

DD-01 © DWT/OPT/0100 ©

175

DWG LOC.
B-6

B-4



ECO # MM11E-00015

D-2C-MM11-E-09

NEW
REV.
A

DWG NO	REV LET	NO OF SHEETS	TITLE
D-IC-MM11-E-09	A	1	I/O CONNECTORS
K-WL-M11-E-07	BC	1	WIRE LIST

ECO # MM11E-00015

A-ML-MM11E

NEW
REV.
P

EQUIPMENT CORPORATION
ENGINEERING
CHANGE ORDER

NO.	DAY	YR.
8	6	70
SPEED RELEASE <i>7/27/77</i>		
TYPE OF CHANGE		
ELECTRICAL		<input checked="" type="checkbox"/>
MECHANICAL		<input type="checkbox"/>
MODULES		<input type="checkbox"/>

CHANGE NO. MM11E-00016

DOCUMENTATION PROJECT NUMBER		
ACT	PROD. LINE	TYPE OR DISCRETE NO.
	110	7428
MANUFACTURING PROJECT NUMBER		
ACT	PROD. LINE	TYPE OR DISCRETE NO.

UNIT NAME PDP-11 MEMORY MODEL NO. MM11E

PREVIOUS OPTIONS AFFECTED

MODEL NO.	VARIATION

CHANGE TESTED IN SERIAL NO. _____ BY _____

ESTIMATED TIME TO INSTALL _____

PARTS ADDED OR DELETED (IF YES REFER TO SEPARATE SHEET)

	YES	NO
SNIP MODEL AFFECTED	<input type="checkbox"/>	<input checked="" type="checkbox"/>
SYSTEMS PROGRAMS AFFECTED	<input type="checkbox"/>	<input checked="" type="checkbox"/>
DIAGNOSTIC PROGRAMS AFFECTED	<input type="checkbox"/>	<input checked="" type="checkbox"/>
TECHNICAL PUBLICATIONS AFFECTED	<input type="checkbox"/>	<input checked="" type="checkbox"/>

BREAK-IN POINT
(DATE/SERIAL NOS.)
SER. #100 THRU 953 AND ALL FUTURE.
ALL IN PROCESS.

PROBLEM:

1. TIMING + FLOW DIAGRAM WRONG.
2. NOT ENOUGH INFORMATION GIVEN ON THE DRAWING TO INSURE THE REQUIRED RESULTS WHEN HAND WIRE WRAPPING. TWISTED PAIRS WILL PICK BACK PLANE NOISE UNLESS DONE CORRECTLY.

CORRECTION:

1. CORRECT TIMING + FLOW DIAGRAM
2. ADDITIONAL INFORMATION PUT ON THE PRINT.

DRAWINGS AFFECTED

NUMBER	OLD	NEW
	REV	REV
A-PL-MM11-E	M	M
D-TD-MM11-E-08	A	B
D-AD-7006468-0-0	B	C
A-PL-7006468-0-0	B	C

FIELD SERVICE CODED


D

ORIGINATOR Richard V. Manion x-2814 DATE 8-2-70
 PRODUCTION ENG. D. Call DATE 8-3-70
 DESIGN ENG. Peter Durant DATE 8-3-70
 OTHER R. J. FARRIER AGK DATE R 4-70


PRODUCT LINES AFFECTED

PDP-11


DWG LOC.
D-4




C 4+3



B-5




B516



D-TD-MM11E-08
ECO# MM11E-00016

LENGTH SHOULD BE A MAXIMUM OF 2 1/4 INCHES. CHECK DRAWINGS FOR LENGTH AND FOR HOW LOOPS SHOULD BE DRESSED INTO LOGIC.



ECO# MM11E-00016 D-AD-7006468-0-0

NEW
REV
C.

ms

DWG NO.	REV LET
D-AD-7006468-0-0	BC
A-PL-7006468-0-0	BC
D-TD-MM11-E-08	AB

ECO# MM11E-00016

A-ML-MM11-E

NEW
REV
N

ENGINEERING CHANGE ORDER				ECO NO. MM11E-00017 Sheet 1 of 4																																				
ORIGINATOR RICHARD MANNION	RECEIVED CHG. DATE 12/22/70	ISSUED ECO DATE 1-22-71	FINAL RELEASE DATE	DISCRETE PROJECT NUMBER 11 07602																																				
EQUIPMENT AFFECTED																																								
TYPE CHANGE ELECTRICAL <input checked="" type="checkbox"/> MECHANICAL <input type="checkbox"/> MODULE <input type="checkbox"/> SUBASSEMBLY <input type="checkbox"/> MFG/FIELD PROCEDURE <input type="checkbox"/> TEST INFORMATION SERIAL # _____ BY _____	UNIT TO BE CHANGED MM11-E PRODUCT LINES PDP11	CHECKLIST <table style="width:100%; border: none;"> <tr> <td style="width:50%;">SHOP MODEL</td> <td style="width:5%; text-align: center;">YES</td> <td style="width:5%; text-align: center;">NO</td> <td style="width:40%;"></td> </tr> <tr> <td>SYSTEMS PROGRAMS</td> <td style="text-align: center;"><input type="checkbox"/></td> <td style="text-align: center;"><input checked="" type="checkbox"/></td> <td></td> </tr> <tr> <td>DIAGNOSTICS</td> <td style="text-align: center;"><input type="checkbox"/></td> <td style="text-align: center;"><input checked="" type="checkbox"/></td> <td></td> </tr> <tr> <td>TECHNICAL PUB</td> <td style="text-align: center;"><input checked="" type="checkbox"/></td> <td style="text-align: center;"><input type="checkbox"/></td> <td></td> </tr> <tr> <td>TEST PROGRAMS</td> <td style="text-align: center;"><input type="checkbox"/></td> <td style="text-align: center;"><input checked="" type="checkbox"/></td> <td></td> </tr> <tr> <td>TESTER</td> <td style="text-align: center;"><input type="checkbox"/></td> <td style="text-align: center;"><input checked="" type="checkbox"/></td> <td></td> </tr> <tr> <td>MFG.FIELD PROCEDURE</td> <td style="text-align: center;"><input type="checkbox"/></td> <td style="text-align: center;"><input checked="" type="checkbox"/></td> <td></td> </tr> <tr> <td>PACKAGING INSTRUCTIONS</td> <td style="text-align: center;"><input type="checkbox"/></td> <td style="text-align: center;"><input checked="" type="checkbox"/></td> <td></td> </tr> <tr> <td>TOOLING</td> <td style="text-align: center;"><input type="checkbox"/></td> <td style="text-align: center;"><input checked="" type="checkbox"/></td> <td></td> </tr> </table>			SHOP MODEL	YES	NO		SYSTEMS PROGRAMS	<input type="checkbox"/>	<input checked="" type="checkbox"/>		DIAGNOSTICS	<input type="checkbox"/>	<input checked="" type="checkbox"/>		TECHNICAL PUB	<input checked="" type="checkbox"/>	<input type="checkbox"/>		TEST PROGRAMS	<input type="checkbox"/>	<input checked="" type="checkbox"/>		TESTER	<input type="checkbox"/>	<input checked="" type="checkbox"/>		MFG.FIELD PROCEDURE	<input type="checkbox"/>	<input checked="" type="checkbox"/>		PACKAGING INSTRUCTIONS	<input type="checkbox"/>	<input checked="" type="checkbox"/>		TOOLING	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
SHOP MODEL	YES	NO																																						
SYSTEMS PROGRAMS	<input type="checkbox"/>	<input checked="" type="checkbox"/>																																						
DIAGNOSTICS	<input type="checkbox"/>	<input checked="" type="checkbox"/>																																						
TECHNICAL PUB	<input checked="" type="checkbox"/>	<input type="checkbox"/>																																						
TEST PROGRAMS	<input type="checkbox"/>	<input checked="" type="checkbox"/>																																						
TESTER	<input type="checkbox"/>	<input checked="" type="checkbox"/>																																						
MFG.FIELD PROCEDURE	<input type="checkbox"/>	<input checked="" type="checkbox"/>																																						
PACKAGING INSTRUCTIONS	<input type="checkbox"/>	<input checked="" type="checkbox"/>																																						
TOOLING	<input type="checkbox"/>	<input checked="" type="checkbox"/>																																						
BREAK IN POINT				SIGNIFICANCE																																				
SYSTEM	MODULE/OPTION MM11-E	FIELD DISTRIBUTED FOR FIELD SERVICE INFORMATICS ONLY	REWORK CODE 05	REQ. TO MEET SPECIFICATION <input type="checkbox"/> PROD IMPROVEMENT <input checked="" type="checkbox"/> CUSTOMER/FIELD REQ. <input type="checkbox"/> FACILITATE MFG. <input type="checkbox"/> DRAWING CORRECTION <input checked="" type="checkbox"/> VENDOR <input type="checkbox"/>																																				
PROBLEM																																								
1. WANTED TO IMPROVE MEMORY PERFORMANCE. STROBE 210 NS WAS TOO EARLY FOR OPTIMUM PERFORMANCE . SOME TIMES CURRENT WAS TOO HIGH FOR OPTIMUM PERFORMANCE WHEN ADJUSTING THE REFERENCE VOLTAGE 2. WIRE LIST WAS NOT CHANGED ACCORDING TO ECO # MM11E-00015. 3 BLOCK SCHEMATIC DOES NOT REFLECT CHANGES OF M729 CIRCUIT SCHEMATIC 4. TIMING AND FLOW DIAGRAM NEEDS TO BE UPDATED. 5. WRITING IN MARGIN																																								
CORRECTION																																								
1. CHANGED TEST PROCEDURE TO IMPROVE MEMORY PERFORMANCE. 2. CORRECT WIRE LIST ACCORDING TO SUBMITTED ADD/DELETE SHEET. 3. UPDATE BLOCK SCHEMATIC PER ATTACHED MARKED UP PRINT. 4. UPDATE TIMING AND FLOW DIAGRAM AS INDICATED . 5. REMOVE WRITING FROM MARGIN.																																								
APPROVAL																																								
DESIGN ENGINEER <u>P. DURANT</u>		ENG MGR _____																																						
PRODUCTION ENGINEER <u>D. CALL</u>		FIELD SERVICE (ADVISORY) <u>J. BUZYNSKI</u>																																						
CHIEF ENGINEER _____																																								

DBA 111A

213E

SEE REVERSE SIDE FOR INSTRUCTIONS

86

**ENGINEERING CHANGE ORDER
DOCUMENT & MATERIAL**

ECO NO

MM11E-00017

Sheet 2 of 4

ITEM	DOC PART NUMBER	OLD REV	NEW REV	(PART NAME) DESCRIPTION OF CHANGE	DISP CODE
1	A-ML-MM11-E	P	R	(MASTER LIST) UPDATE REVISION LEVEL ON THE FOLLOWING DRAWINGS: D-BS-MM11-E-05 FROM A TO B K-WL-MM11-E-07 FROM C TO D D-TD-MM11-E-08 FROM B TO C A-SP-MM11-E-11 FROM O TO A	06
2	D-BS-MM11-E-05	A	B	(BLOCK SCHEMATIC) SEE MARKED PRINT THIS ECO.	06
3	K-WL-MM11-E-07	C	D	(WIRE LIST) SEE ADD/DELETE SHEET THIS ECO.	06
4	D-TD-MM11-E-08	B	C	(TIMING DIAGRAM) DELETE CHECK RACE COND. IN MARGIN. INCREASE TIME AND FLOW IN DISZ BEFORE 650NS. INCREASE TIME AND FLOW IN CINZ BEFORE 350 NS.	06
5	A-SP-MM11-E-11	-	A	(ENGINEERING SPECIFICATION) DELETE FROM PARA. 11.0 210 NS . ADD 220NS. ADD TO PARA. 13.4- IF THE MARGIN IS GREATER THAN 1.0V SET VXY AT 0.5 BELOW THE FAILING HIGH END POINT. (EXAMPLE IF MARGINS ARE 0.4 TO 1.8V, SET AT 1.3V= 1.8-0.5)	06


DISPOSITION CODES

Use up Present Stock	01	Retrol t to Break in	06
Use Present Stock until New Stock Available	02	Documentation Change Only	08
Rework all Material	03	New Item Purchase	07
Rework until New Stock Available	04	New Item in Stock	08
		New Item on Order	09
		Retain	00

SEE REVERSE SIDE FOR INSTRUCTIONS

DRA 112A

06



ECO* MM1E-0001?

C-BS-MM11-E-05

NEW
REVB

ENGINEERING CHANGE ORDER
 W.O. 362E CS DM ECO NO MM11E-00020
 Sheet 1 of 3

ORIGINATOR RICHARD MANNION	RECEIVED CHG. DATE 3/24/71	ISSUED ECO DATE 3-26-71	FINAL RELEASE DATE 4-13-71	DISCRETE PROJECT NUMBER 11 07602
DATE 3/9/71	EXT 2005			

EQUIPMENT AFFECTED

TYPE CHANGE	UNIT TO BE CHANGED	CHECKLIST	YES	NO
ELECTRICAL <input checked="" type="checkbox"/>	MM11E	SHOP MODEL	<input type="checkbox"/>	<input checked="" type="checkbox"/>
MECHANICAL <input type="checkbox"/>	PRODUCT LINES	SYSTEMS PROGRAMS	<input type="checkbox"/>	<input checked="" type="checkbox"/>
MODULE <input type="checkbox"/>		DIAGNOSTICS	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
SUBASSEMBLY <input type="checkbox"/>	PDP11	TECHNICAL PUB	<input checked="" type="checkbox"/>	<input type="checkbox"/>
MFG/FIELD PROCEDURE <input type="checkbox"/>		TEST PROGRAMS	<input type="checkbox"/>	<input checked="" type="checkbox"/>
TEST INFORMATION		TESTER	<input type="checkbox"/>	<input checked="" type="checkbox"/>
SERIAL #		MFG/FIELD PROCEDURE	<input checked="" type="checkbox"/>	<input type="checkbox"/>
BY		PACKAGING INSTRUCTIONS	<input type="checkbox"/>	<input checked="" type="checkbox"/>
		TOOLING	<input type="checkbox"/>	<input checked="" type="checkbox"/>

BREAK IN POINT			SIGNIFICANCE		
SYSTEM	MODULE/OPTION	FIELD	REWORK	CODE	
FIELD SERVICE	MM11E	DISTRIBUTED FOR FIELD SERVICE INFORMATION ONLY		06	REQ TO MEET SPECIFICATION <input type="checkbox"/>
					PROD IMPROVEMENT <input checked="" type="checkbox"/>
					CUSTOMER/FIELD REQ <input type="checkbox"/>
					FACILITATE MFG <input type="checkbox"/>
					DRAWING CORRECTION <input checked="" type="checkbox"/>
					VENDOR <input type="checkbox"/>

PROBLEM

- 1) WANTED TO IMPROVE MEMORY PERFORMANCE. STROBE AT 220 NS AS SUGGESTED IN ECO MM11E-00017 WAS TOO LATE FOR OPTIMUM PERFORMANCE
- 2) PAR 12.0 MM11E TEST PROCEDURE INCORRECT. V THRESHOLD SET TO -5.3V IS TOO LOW.

CORRECTION

- 1) CHANGE STROBE SETTING AS STATED IN PARAGRAPH 11.0 FROM 220 NS TO 210 NS
- 2) CHANGE TEST PROCEDURE . SET V THRESHOLD AT -5.2V

NOTE: REF. ECO MM11E-00017 PROBLEM 1. IF THE CORRECTION FOR PROBLEM (1) IN ECO MM11E-00017 WAS NOT PERFORMED IT WILL NOT BE NECESSARY TO IMPLEMENT CORRECTION (1) OF THIS ECO.

APPROVAL

DESIGN ENGINEER P DURANT 3/2/71 ENG MGR _____
 PRODUCTION ENGINEER DON CALL 3/3/71 FIELD SERVICE _____
 CHIEF ENGINEER _____ (ADVISORY) J. BUZYNSKI

DRA 111A

SEE REVERSE SIDE FOR INSTRUCTIONS

**ENGINEERING CHANGE ORDER
DOCUMENT & MATERIAL**

ECO NO
MM11E-00020
Sheet 2 of 3

ITEM	DOCUMENT OR PART NUMBER	OLD REV	NEW REV	(PART NAME) DESCRIPTION OF CHANGE	DISP CODE
1	A-ML-MM11-E	T	U	(MASTER LIST) UPDATE REVISION LEVEL OF ITEM 3 THIS ECO	06
2	A-ML-MM11-EX	-	A	(MASTER LIST) SAME CHANGE AS ITEM 1 THIS ECO	06
3	A-SP-MM11E-11	A	B	(TEST PROCEDURE) SHEET 4 OF 5: DELETE 220 MS IN PARAGRAPH 11.0 ADD 210 MS DELETE -5.3V IN PARAGRAPH 12.0 ADD -5.2V UPDATE REVISION LEVEL ON ALL SHEETS	06

DISPOSITION CODES

Use up Present Stock	01	Retrofit to Break in	05
Use Present Stock until New Stock Available	02	Documentation Change Only	06
Rework all Material	03	New Item Purchase	07
Rework until New Stock Available	04	New Item in Stock	08
		New Item on Order	09
		Retain	00

SEE REVERSE SIDE FOR INSTRUCTIONS

DRA 112A

06

FIELD SERVICE NOTES:

ECO MM1E-00020
Page 3 of 3

C LEVEL OF URGENCY code

The ECO number will be posted to the EDP file with this LOU code replacing the lead # - "A" = Mandatory, High Priority
"B" = Mandatory "C" = Applicable if symptoms are present
"D" = Low Priority "D" = Product Improvement, Optional

Yes This ECO is NO CHARGE TO CUSTOMER - All DEC installation labor and materials are to be reported under a "W" charge code.

No This ECO is STANDARD APPLICABILITY - It is to be installed at no charge for warranty and maintenance contract customers in accordance with the technical effectivity, otherwise at customer expense.
Charges - Documentation \$ N/C, Parts \$ NONE,
DEC on-site labor \$ N/C. (minimum per call billing applies)
(* parts prices not available at the time of Speco release)

F FIELD DISTRIBUTION CODE

"F" = Immediate Speco distribution to all field offices
"DF" = No general Speco distribution, only to offices where equipment is located (less than 25 units in the field)

No UNCONDITIONAL ECO - General distribution kits will include Field Installation Orders, Specos, Prints, and Parts.

Yes CONDITIONAL ECO - General distribution will include Field Installation Orders only. Prints and parts must be ordered from FSIC as required.

No Parts availability delay expected _____.

Yes The REQUIREMENT TO MEET SPECIFICATION is applicable retroactively to equipment in the field.

NOTE:



ENGINEERING
CHANGE ORDER 8527

ORIGINATOR Richard Manion *5-2*
TEL EXT 2005 DATE 3/13/72
DISC PROJ NO 11 07602
COST CENTER NO 392 *A.F*

ECO NO. *MM11E-00028*
SHEET *1* OF *3*
DATE RECEIVED *3-16-72*
FIRST ISSUE *3-20-72*
FINAL ISSUE

PROBLEM
Under some conditions when other options are placed along side an MM11/E they fail to operate correctly.

UNIT TO BE CHANGED

MM11/E
Memory

DISP CODE ~~34~~

OPTIONS AFFECTED

MM11/E

CORRECTION
Install a module protection plate.

BREAK IN/EFFECTIVITY
*Install module protection plate only when problems occur.

PRODUCT LINES
AFFECTED

PDP11/20

ITEM NO	DOCUMENT/PART NO	OLD REV	NEW REV	DISP CODE	DESCRIPTION OF CHANGE	DOCUMENTATION AFFECTED	FIELD SERVICE AFFECTED	TYPE OF CHANGE	ORDER PR MODEL
1.	C-DI-MM11-E-01	0	E	06	(Drawing Index Memory) Change per this ECO.	<input type="checkbox"/> MODEL <input type="checkbox"/> DIAGNOSTICS <input type="checkbox"/> TECH MANUAL <input type="checkbox"/> TESTER <input type="checkbox"/> TEST PROG <input type="checkbox"/> TOOLING <input type="checkbox"/> PKG INST <input type="checkbox"/> ENG SPEC <input type="checkbox"/> PURCH SPEC	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> Customer Change <input checked="" type="checkbox"/> Product Line Change	<input type="checkbox"/> ELECTRICAL <input checked="" type="checkbox"/> MECHANICAL <input type="checkbox"/> MODULE	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
2.	7408490	-	-	07	(Module Protection Plate) Add quantity of 1 to drawing index.				
3.	A-ML-MM11-E	V	W	06	Update per item 1.				

DISPOSITION CODES

APPROVAL SIGNATURES

00 RETURN TO STOCK
01 DELETED
02 USE PRESENT STOCK UNTIL NEW STOCK AVAILABLE (PHASE IN)
03 REV ORK IMMEDIATELY (RETROFIT)
04 (DELETED)
05 (DELETED)
06 DOCUMENT CORRECTION
07 NEW ITEM (THIS ASSEMBLY)
08 NEW ITEM (THIS COMPANY)
09 SCRAP IMMEDIATELY

Typewritten Name Signature
DESIGN ENGR Pete Durant *Pete Durant*
ENG MGR (OPT) _____
FIELD SERVICE (OPT) _____
CHIEF ENGR (MODULES ONLY) *R. G. D.*



FIELD CHANGE ORDER

FCO MM11E D0022
PAGE 2 OF 2

DATA PROCESSING AND DEC-ECO LOGS WILL POST THIS FCO WITH THE LEVEL OF URGENCY CODE REPLACING THE LEADING ZERO.

FIELD EFFECTIVITY

MM11-E Memory Assembly

FIELD RETROFIT IS ANTICIPATED IN 5 % OF UNITS DEFINED ABOVE

- NO CHARGE TO CUSTOMER ALL DEC INSTALLATION LABOR AND MATERIAL ARE TO BE REPORTED UNDER A "W" CHARGE CODE
 - STANDARD APPLICABILITY THIS FCO IS TO BE INSTALLED AT NO CHARGE FOR WARRANTY AND MAINTENANCE CONTRACT CUSTOMERS IN ACCORDANCE WITH THE TECHNICAL EFFECTIVITY ABOVE OTHERWISE AT CUSTOMER EMP. 44
- DOCUMENTATION 8 PARTS 8 DEC ON-SITE LABOR 8
- DEC'S MINIMUM BILLING APPLIES IF THIS FCO IS INSTALLED BY DEC THE DEC LABOR CHARGE ASSURES FCO INSTALLATION DURING REGULAR WORKING HOURS IF INSTALLATION OUTSIDE OF REGULAR WORKING HOURS IS ORDERED, DEC'S LATEST SCHEDULE OF HOURLY RATES WILL APPLY

FIELD OFFICE FCO DISTRIBUTION CODE

- F IMMEDIATE FCO DISTRIBUTION TO ALL DEC FIELD OFFICES
- DE IMMEDIATE FCO DISTRIBUTION TO REGIONAL PRODUCT SUPPORT AND TO OFFICES WHERE SUBJECT EQUIPMENT IS LOCATED

FCO KIT DISTRIBUTION

- PSIC WILL INITIATE DISTRIBUTION OF FCO KITS AS DEFINED BELOW IN ACCORDANCE WITH THE EDP CONFIGURATION FILE
- ~~PSIC WILL INITIATE DISTRIBUTION OF FCO KITS AS DEFINED BELOW IN ACCORDANCE WITH THE EDP CONFIGURATION FILE~~ KITS AS DEFINED BELOW MAY BE ORDERED AS FEATURED

CONTENTS OF AN PSIC INITIATED KIT

FID	FCO	PRINTS	PARTS

CONTENTS OF A FIELD ORDERED KIT

FID	FCO	PRINTS	PARTS
	X	X	X

PSIC INITIATED FCO KITS WILL BE DISTRIBUTED FOR ALL UNITS LISTED ON THE EDP CONFIGURATION FILE WITH THE FOLLOWING SERVICE STATUS CODES

D	H	K	B
---	---	---	---

- PRINT CHANGES ARE MINIMA, AND ARE TO BE MADE MANUALLY IN RED AND GREEN FCO REVISED PRINTS WILL BE SUPPLIED ONLY UPON SPECIAL REQUEST

INSTALLATION AND TEST PROCEDURES

- Carefully install module protection plate per FCO instructions. This requires insertion of the plate under existing wire runs which are easily broken.
- Run maindecs or other programs whose failure indicated the need for this FCO to be implemented. They should now function correctly.

NOTES

- * LEVEL OF URGENCY CODE
- A MANDATORY HIGH PRIORITY
- B MANDATORY
- C HIGH PRIORITY IF SPECIFIC HARDWARE, SOFTWARE, OR SYMPTOMS ARE PRESENT
- D APPLICABLE IF SPECIFIC HARDWARE SOFTWARE OR SYMPTOMS ARE PRESENT
- E PRODUCT IMPROVEMENT - OPTIONAL - LOW PRIORITY

DISK RATE PROJECT NUMBER (FOR FIELD SERVICE REPORTING)

AVAILABILITY DELAY NONE NO PARTS

ESTIMATED DOWN TIME FOR INSTALLATION AND TESTING 1.0 HOURS

SPECIAL TEST EQUIPMENT, TOOLS, OR SUPPLIES

LAST PREVIOUS FCO'S C020, C016, 015

- RELATED OR PREREQUISITE FCO'S
- MAINDEC CHANGE
- MAINTENANCE MANUAL CHANGE
- OPERATIONAL PROGRAMS AFFECTED

VERIFICATION MANDECS

PARTS REQUIRED
Q1 74-09490 Module Protection Plate

FIELD SERVICE APPROVAL
Charles Dewey


CDK
1/30 3/24 (0) 3/24 75

THIS DOCUMENT WAS NOT PRODUCED FOR MICROFICHE; THEREFORE, ONLY PARTS OF IT ARE READABLE.

ECO MM11E-00022
MM11F REWORK SHEET

SHEET 2 OF 2

1. LOOSEN 2 SCREWS AT POINTS A, CARE SHOULD BE USED AT ALL TIME SO THAT NO WIRES WILL BE DAMAGED.
2. SLIDE THE FINGERS OF THE MODULE PROTECTION PLATE UNDER THE GND LUGS. THE PROTECTION PLATE SHOULD BE RIGHT AGAINST THE WIRED ASSY. FRAME, POINTS B.
3. TIGHTEN SCREWS.



<p>ENGINEERING CHANGE ORDER</p>	TITLE	DWG NO	BY
	JRN ALYCE FURTRDD		
	CHG NO <i>C-11</i>	CHG LOC	GRAPHIC DESCRIPTION

ENGINEERING CHANGE ORDER	ORIGINATOR R. Manion 1-3	ECO NO. <u>MM11-E-0074</u>
	TEL EXT 2005 DATE 5-6-72	SHEET <u>1</u> OF <u>1</u>
	DESC PROJ NO. D-96-6122	DATE RECEIVED <u>5-9-72</u>
	COST CENTER NO. 392 <u>A.F.</u>	FIRST ISSUE <u>5-10-72</u>
		FINAL ISSUE <u>6-26-72</u>

PROBLEM 1. STROBE Signals and TINH have too much noise on them. 2. Read H signal has too many loads on it.	UNIT TO BE CHANGED MM11-E
	DISP CODE 03

CORRECTION 1. Install twisted pairs for these signals. 2. Develop another Read H signal to share the load.	OPTIONS AFFECTED MM11-E
--	----------------------------

BREAK-IN/EFFECTIVITY All MM11-E's shipped after May 12 will have this ECO. Rework M729 Module when necessary, all MM11E's with this ECO, MUST have M729's with ECO # 2.	PRODUCT LINES AFFECTED PDP-11/45 PDP-11/20 PDP-11/45
---	---

ITEM NO	DOCUMENT/PART NO.	OLD REV	NEW REV	DISP CODE	DESCRIPTION OF CHANGE	DOCUMENTATION AFFECTED	FIELD SERVICE AFFECTED	TYPE OF CHANGE
1	K-WL-MM11-E-07	D	E	06	Wire List Update	<input type="checkbox"/> MODEL	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> ELECTRICAL
2	D-AD-7006468-0-0	D	E	06	Wire Ass'y MM11-E See final release print.	<input type="checkbox"/> DIAGNOSTICS	<input type="checkbox"/> Customer Charge	<input type="checkbox"/> MECHANICAL
3	D-BS-MM11-E-03	A	B	06	Core Memory stack (2 sheets) See final release print.	<input type="checkbox"/> TECH MANUAL	<input checked="" type="checkbox"/> Product Line Change	<input type="checkbox"/> MODULE
4	A-PL-MM11-E	Z	AA	06	UPDATE PRINT PER THIS ECO.	<input type="checkbox"/> TESTER		ORDER PR MODEL
5	E-DI-MM11-E-01	E	F	06	UPDATE PRINT PER THIS ECO	<input type="checkbox"/> TEST PROG		<input type="checkbox"/> YES
6	A-PL-7006468-0-0	D	E	06	UPDATE REV PER THIS E.C.O.	<input type="checkbox"/> TOOLING		<input type="checkbox"/> NO
						<input type="checkbox"/> PKG INST		
						<input type="checkbox"/> ENG SPEC		
						<input type="checkbox"/> PURCH SPEC		

DISPOSITION CODES 00 - RETURN TO STOCK 01 - (DELETED) 02 - USE PRESENT STOCK UNTIL NEW STOCK AVAILABLE (PHASE IN) 03 - REWORK IMMEDIATELY (RETROFIT) 04 - (DELETED) 05 - (DELETED) 06 - DOCUMENT CORRECTION 07 - NEW ITEM (THIS ASSEMBLY) 08 - NEW ITEM (THIS COMPANY) 09 - SCRAP IMMEDIATELY	APPROVAL SIGNATURES Type/Hand Signature DESIGN ENGR <u>PREL DURANT</u> ENG MGR (OPT) _____ FIELD SERVICE (OPT) _____ CHIEF ENGR (MODULES ONLY) _____
--	--

ENGINEERING CHANGE ORDER ADD/DELETE SHEET

ECO NO
MM1E-00024
Sheet ___ of ___


WIRE LIST NO. **K-WL-MM1E-07**

TITLE
MM1E

MAKE ALL DELETIONS FIRST WHEN INSTALLING


SIGNAL NAME	FROM PIN	TO PIN	COMPONENTS	ADD	DEL
READ H	C02V2	D01A1	REMARKS		X
READ 01 H	C01F2	C02C1		X	
STROBE 01 H	C01F1	D02S1			X
STROBE 01 H	C01A1	E02S1			X
TINH 0 H	D02E1	E01S1			X
TINH 1 H	E01H2	F01F1			X
STROBE 0 H	C01F1	D02S1	WHT	X	
GND	C01C2	D02T1	BLK		X
STROBE 01 H	C01A1	E02S1	WHT	X	
GND	C01C2	E03T1	BLK		X
T 01 H	E01S1	D02E1	WHT	X	
GND	E01C2	D01C2	BLK		X
T 1 H	E01H2	F01E1	WHT	X	
GND	E01C2	F01C2	BLK		X

4.3


	<h2 style="margin:0;">FIELD CHANGE ORDER</h2>	<p>FCO <u>MM11E - B 0024</u> PAGE <u> </u> OF <u> </u></p> <p><small>DATA PROCESSING AND DEC ECO-LOG WILL POST THIS FCO WITH THE LEVEL OF URGENCY CODE REPLACING THE LEADING ZERO</small></p> <p>• LEVEL OF URGENCY CODE</p> <p>A MANDATORY HIGH PRIORITY B MANDATORY C HIGH PRIORITY IF SPECIFIC HARDWARE SOFTWARE, OR SYMPTOMS ARE PRESENT D APPLICABLE IF SPECIFIC HARDWARE SOFTWARE, OR SYMPTOMS ARE PRESENT E PRODUCT IMPROVEMENT OPTIONAL LOW PRIORITY</p>																
<p>FIELD EFFECTIVITY Retrofit all MM11-E's</p>		<p>CONCRETE PROJECT NUMBER (FOR FIELD SERVICE REPORTING)</p> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:50%;">AVAILABILITY DELAY</td> <td style="width:50%;">NO PARTS</td> </tr> <tr> <td>PARTS</td> <td style="text-align: center;">X</td> </tr> <tr> <td colspan="2">ESTIMATED DOWN TIME FOR INSTALLATION AND TESTING 1.0 HOURS</td> </tr> <tr> <td colspan="2">SPECIAL TEST EQUIPMENT, TOOLS OR SUPPLIES</td> </tr> </table> <p>LAST PREVIOUS FCO'S <u>D022, C020, C017</u> RELATED OR PREREQUISITE FCO'S <u>M729-00003</u></p> <p><input type="checkbox"/> MAINTDEC CHANGE <input type="checkbox"/> MAINTENANCE MANUAL CHANGE <input type="checkbox"/> OPERATIONAL PROGRAMS AFFECTED</p> <p>VERIFICATION MAINDECS</p> <p>PARTS REQUIRED</p>	AVAILABILITY DELAY	NO PARTS	PARTS	X	ESTIMATED DOWN TIME FOR INSTALLATION AND TESTING 1.0 HOURS		SPECIAL TEST EQUIPMENT, TOOLS OR SUPPLIES									
AVAILABILITY DELAY	NO PARTS																	
PARTS	X																	
ESTIMATED DOWN TIME FOR INSTALLATION AND TESTING 1.0 HOURS																		
SPECIAL TEST EQUIPMENT, TOOLS OR SUPPLIES																		
<p>FIELD RETROFIT IS ANTICIPATED IN <u>100</u> OF UNITS DEFINED ABOVE</p> <p><input checked="" type="checkbox"/> NO CHARGE TO CUSTOMER ALL DEC INSTALLATION LABOR AND MATERIAL ARE TO BE REPORTED UNDER A "W" CHARGE CODE</p> <p><input type="checkbox"/> STANDARD APPLICABILITY THIS FCO IS TO BE INSTALLED AT NO CHARGE FOR WARRANTY AND MAINTENANCE CONTRACT CUSTOMERS IN ACCORDANCE WITH THE TECHNICAL EFFECTIVITY ABOVE OTHERWISE AT CUSTOMER EXPENSE</p> <p>DOCUMENTATION S <u> </u> PARTS S <u> </u> DEC ON SITE LABOR S <u> </u></p> <p><small>DEC'S MINIMUM BILLING APPLIES IF THIS FCO IS INSTALLED BY DEC THE DEC LABOR CHARGE ASSUMES FCO INSTALLATION DURING REGULAR WORKING HOURS IF INSTALLATION OUTSIDE OF REGULAR WORKING HOURS IS ORDERED DEC'S LATEST SCHEDULE OF HOURLY RATES WILL APPLY</small></p>																		
<p>FIELD OFFICE FCO DISTRIBUTION CODE</p> <p><input checked="" type="checkbox"/> F IMMEDIATE FCO DISTRIBUTION TO ALL DEC FIELD OFFICES <input type="checkbox"/> D IMMEDIATE FCO DISTRIBUTION TO REGIONAL PRODUCT SUPPORT AND TO OFFICES WHERE SUBJECT EQUIPMENT IS LOCATED</p>																		
<p>FCO KIT DISTRIBUTION</p> <p><input type="checkbox"/> PSIC WILL INITIATE DISTRIBUTION OF FCO KITS AS DEFINED BELOW IN ACCORDANCE WITH THE EDP CONFIGURATION FILE</p> <p><input checked="" type="checkbox"/> PSIC WILL INITIATE DISTRIBUTION OF FCO KITS AS DEFINED BELOW IN ACCORDANCE WITH THE EDP CONFIGURATION FILE KITS AS DEFINED BELOW MAY BE ORDERED AS REQUIRED</p>																		
<p>CONTENTS OF AN PSIC INITIATED KIT</p> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>FID</th> <th>FCO</th> <th>PRINTS</th> <th>PARTS</th> </tr> <tr> <td> </td> <td> </td> <td> </td> <td> </td> </tr> </table> <p>CONTENTS OF A FIELD ORDERED KIT</p> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>FID</th> <th>FCO</th> <th>PRINTS</th> <th>PARTS</th> </tr> <tr> <td> </td> <td style="text-align: center;">X</td> <td style="text-align: center;">X</td> <td> </td> </tr> </table>		FID	FCO	PRINTS	PARTS					FID	FCO	PRINTS	PARTS		X	X		<p><small>PSIC INITIATED FCO KITS WILL BE DISTRIBUTED FOR ALL UNITS LISTED ON THE EDP CONFIGURATION FILE WITH THE FOLLOWING SERVICE STATUS CODES</small></p> <p style="text-align: center;">D H K W</p>
FID	FCO	PRINTS	PARTS															
FID	FCO	PRINTS	PARTS															
	X	X																
<p><input type="checkbox"/> PRINT CHANGES ARE MINIMAL AND ARE TO BE MADE MANUALLY IN RED AND GREEN FCO REVISED PRINTS WILL BE SUPPLIED ONLY UPON SPECIAL REQUEST</p> <p>INSTALLATION AND TEST PRETIRBS</p>																		
<p>NOTES Necessary to improve reliability on existing units.</p>																		
<p>FIELD SERVICE OFFICIAL <u> </u></p>		<p><u> </u> 5/11 5/17 (1534) 5/17 800</p>																

THIS DOCUMENT WAS NOT PRODUCED FOR MICROFICHE THEREFORE, ONLY PARTS OF IT ARE READABLE.

A)



ENGINEER NO CHANGE ORDER	CORP. MEMORY STACK (X DRIVE)		Dwg No. D-03-MM115-03	REV B
	DATE	BY		




SHEET 2 of 2

	CORE MEMORY STACK (Y DRIVE)	D-05-MM16-03	REV B
	<i>Alvin Smith</i>		
NGI 1116 1/14/64			GRAPHIC DESCRIPTION

WIRE TABLE

SIGNAL NAME	FROM PIN	TO PIN	COLOR	REMARKS	SIGNAL NAME	FROM PIN	TO PIN	COLOR	REMARKS
STROBE BN GND	C01A1 C01C2	D05E1 D05T1	WHT BLK	TWP	TO INH GND	E01S1 E01C2	D05E1 D05C2	WHT BLK	TWP
					T1 INH GND	E01N2 E01C2	F01E1 F01C2	WHT BLK	TWP
					STROBE BN GND	G01D1 G01C2	D05S1 D05T1	WHT BLK	TWP

ADD

 ENGINEER NO CHANGE ORDER	WIRED ASS'Y ILL MM116-B	NO. D-AD-700147-1-0	116
	DESIGNED <i>Alvin [Signature]</i>	CHECKED <i>Cathy</i>	DATE 6-2

FCR

**MM11-E
PDP-11 MEMORY
FCO Cross Reference**

**A Chronological Listing of Field Retrofit FCO's Which Must Be
Considered in the Field Installation and Maintenance of This Option/Module/Power Supply**

• Indicates FCO Conjunction Must Be Considered With Prior FCO

- | | |
|---|---|
| <p>■ G102-B0002 MAR 70
G102-B0003
QUICK SYNOPSIS
8881 IC's replaced by higher speed 74H011 IC's
QUICK CHECK
74H011 IC's in place of 8881 IC's
NEW REVISION
Exchange with CS B or later</p> | <p>■ G103-C0005 JUN 70
QUICK SYNOPSIS
Provides increase to -8.5VDC for sense amplifiers
QUICK CHECK
Heat sink ADD'ed to Q4 C1 and C2 changed from 1000mmfd to 820mmfd
NEW REVISION
Rework etch D E to CS D</p> |
| <p>■ G103-C0002 MAR 70
QUICK SYNOPSIS
Increases system speed
QUICK CHECK
7410 IC replaced by 74H10 IC
NEW REVISION
Rework etch B, C to CS B</p> | <p>■ G225-C0003 JUL 70
QUICK SYNOPSIS
Speeds stabilization of X and Y current generator reference voltage
QUICK CHECK
R22 changed from 4.7K ohms to 2.2K ohms
NEW REVISION
Rework etch B to CS B</p> |
| <p>■ G103-C0004 APR 70
QUICK SYNOPSIS
Provides new higher value trimpot
QUICK CHECK
R17 changed from 100 ohm to 500 ohm trimpot
NEW REVISION
Rework etch B, C to CS C</p> | <p>■ MM11E-C0016 AUG 70
QUICK SYNOPSIS
Provides wire table and wiring instructions to ensure correct memory margins and G102 interchangeability</p> |
| <p>■ G102-B0004 JUN 70
QUICK SYNOPSIS
Decreases turn off time of the 2007 transistors
QUICK CHECK
C2 C7, C12 C17 changed from 1000mmfd to 820mmfd
NEW REVISION
Rework etch D to CS D</p> | <p>■ MM11E-A0015 SEP 70
QUICK SYNOPSIS
Connects AC LO L and DC LO L signal from the Power Bus to the Unibus to ensure proper Power Fail
QUICK CHECK
BUS AC LO L tied to pin F1
NEW REVISION
Rework to Wire List B</p> |

**MM11-E
PDP-11 MEMORY
FCO Cross Reference**

**A Chronological Listing of Field Retrofit FCO's Which Must Be
Considered in the Field Installation and Maintenance of This Option/Module/Power Supply**

• Indicates FCO Conjunction Must Be Considered With Prior FCO

- **M930-C0001 AUG 70**
QUICK SYNOPSIS
Power Fail requires BUS SP1 and BUS SP2 for AC LO and DC LO (In-plant. new etch B at CS A)
QUICK CHECK
R57 and R89 are 390 ohms
NEW REVISION
Rework etch B to CS A
- **B408475-C0008 OCT 70**
QUICK SYNOPSIS
AC LO and DC LO returns high after assertion in multiple box systems
QUICK CHECK
D003 clamping diodes from AC LO (anode) and from DC LO to +5V line
NEW REVISION
Rework etch A, B, C to CS D
- **MM11E-C0017 JAN 71**
MM11E-C0020
QUICK SYNOPSIS
Improves memory performance
QUICK CHECK
Wire ADD B04F2 to A03S2
- **M729-C0002 JAN 71**
QUICK SYNOPSIS
Reduces memory cycle time on systems with 8K interleaved memory (In-plant new etch C)
QUICK CHECK
Wire ADD E9 pin 2 to feed thru near E5 pin 1
NEW REVISION
Rework etch B to CS B
- **M1091-C0001 MAR 71**
QUICK SYNOPSIS
Provides 1 unit load on BUS in systems with 16K or more memory
QUICK CHECK
M1091 replaced M109 module
NEW REVISION
Rework etch B to CS A
- **G102-B0006 APR 71**
QUICK SYNOPSIS
Eliminates MM11-F's noise susceptibility
QUICK CHECK
C3 C8 C13 C18 changed from 33mmfd to 120mmfd
NEW REVISION
Rework etch D to CS D
- **G225-C0007 MAY 71**
QUICK SYNOPSIS
Prevent heat sinks from shorting to etch
QUICK CHECK
Insulating washers under heat sinks
- **M7290-C0002 OCT 71**
QUICK SYNOPSIS
Prevents Unibus hang with SSYN asserted from memory (In-plant new etch E)
QUICK CHECK
Wire ADD E8 pin 5 to E7 pin 9
NEW REVISION
Rework etch C to CS D
- **MM11E-D0022 MAR 77**
QUICK SYNOPSIS
Module protection plate prevents MM11 E noise interaction with adjacent modules
QUICK CHECK
Presence of protection plate
- **MM11E-B0024 MAY 72**
QUICK SYNOPSIS
Reduces noise on TINH and strobe signals
QUICK CHECK
Wire ADD C01F1 to D02S1/C01C2 to D02T1
NEW REVISION
Rework to Wire List E

**MM11-E
PDP-11 MEMORY
FCO Cross Reference**

**A Chronological Listing of Field Retrofit FCO's Which Must Be
Considered in the Field Installation and Maintenance of This Option/Module/Power Supply**

• Indicates FCO Conjunction Must Be Considered With Prior FCO

☐ M729-C0003 MAY 72
M729-D0004
QUICK SYNOPSIS
Unibus hangs with S5YN asserted from
memory
QUICK CHECK
Wire ADD E5 pin 8 to E3 pin 1
NEW REVISION
Rework etch B. C to CS C

☐ M7290-C0003 MAY 72
QUICK SYNOPSIS
Reduced inductance of the TINH H etch cor
rects noise condition (In-plant new etch F)
QUICK CHECK
Wire ADD E11 pin 8 to feed thru going to
AR1
NEW REVISION
Rework etch C D to CS E

ECO
QUICK CHECK

27

MM11-E/F FIELD CODED ECO's

G102	B2, B3, C4, B6
G103	C2, C4, C5, C7
G225	C3, C7
G226	C4
M729	B2, C3 & A & B
M1091	C1
M7290	C2, C3
MM11-E	C15, C16, C17, C20, D22, B24
MM11-F	D1, C3

MM11-E/F ECO PARTS

<u>NAME</u>	<u>ECO#</u>	<u>QTY</u>	<u>PART NUMBER</u>	<u>COMMENTS & DESCRIPTION</u>
G102	#2	1	19-09849	I.C.
	#3	8	13-03064	Resistor
	#4	4	10-00027	Capacitor
		4	13-09995-0	Resistor
		1	16-09996-0	Indicator
	#6	4	10-00018	Capacitor
G103	#2	3	19-09057	I.C.
	#4	1	13-05631	Resistor
	#5	2	13-02602	Resistor
		2	13-09994-0	Resistor
		1	13-00295	Resistor
		2	10-00027	Capacitor
		1	11-09991	Diode
		1	11-09990	Diode
		1	16-09996-0	Conductor
		1	12-10001-0	Heat sink
	#7	1	10-10274	Capacitor
G225	#3	1	13-00417	Resistor
	#7	4	90-08493	Washers
		A/R	90-08268	Thermal compound
G226	#4	1	10-10274	Capacitor
M792	#3	1	19-05547	I.C.
M1091	#1	1	M1091 etch "B"	if applicable module
MM11-F	#1	1	74-08490	Memory shield
MM11-E	#2	1	74-08490	Memory shield

MM11-E/F PARTS BREAKDOWN

7006405	- Logic Frame
7006468	- MM11-E Wired assembly
70007263	- MM11-F Wired assembly
G102	- Sense Inhibit Card
G103	- Memory Levels & Gates
G225	- X-Y Current Generator
G226	- X-Y Current Generator
H207	- 4K 16 Bit Core Memory Stack
M109	- Device Select
M729	- MM11-E Control Logic
M1091	- Device Select
M7290	- Control Logic & Timing
MM11-E	- 4K Single Memory Unit
MM11-EX	- 4K Interleaved
MM11-F	- 4K Single Memory Unit
MM11-FP	- Single Parity Memory Unit
MM11-FX	- Interleaved Memory (jumpers)

MM11-E MEMORY		ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 1 OF 2
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO		QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME
00002	01/70		A		Jumper D01-B1 to E01-E1			NIL					
00003	01/70				Black wire of twisted pair from C02-C2 to E03-C2			NIL					
00006	02/70		B		Jumper A01-S2 to A04-S2			NIL					
C 00015	09/70		C		NOTE: 1) Rework multiple box systems only 2) Must have ECO 5408475-00006 and M930-00001 Jumper A03-S2 to B04-F2			NIL					
C 00016	12/70			1.5	Blue jumper from E01-C1 to E01-E2 looping through logic			NIL					
C 00017	01/71		D		Jumper B04-F1 to A03-R2			NIL					
C 00020	03/71				NOTE: F/S information regarding strobe and threshold level settings			NIL					
D 00022	04/71			1.0	A module protection plate along MM11-E memory bank		1	74-08490					
B 00024	06/72		E	1.0	NOTE: Must have ECO M729 #3 Black wire of twisted pair from E01-C2 to F01-C2.			NIL					

m7

MM11-E		MEMORY		ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 2 OF 2
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
00025	05/76				NOTE: Documentation change				NIL						

MM11-F 4K 16 BIT MEMORY		ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO	QTY.	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
D 00001	3/72			1.0	A module protection plate along each MM11-F bank.	1	74-08490						
00002	5/72				<u>NOTE:</u> Print update of test procedure		Nil						
C 00003	8/72		A	1.0	<u>NOTE:</u> Must have ECO M7290-C0003 Red jumper C01-C2 to E01-T1		Nil						

G102 SENSE INHIBIT CARD				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
00001	3/70		C		<u>NOTE:</u> Documentation change				Nil						
B 00002	3/70	B	D	0.5	E5 is a DEC I.C. <u>74H01-1</u> E5 is the 1st I.C. from AS1			1	19-09849						
B 00003	4/70	B	D		<u>NOTE:</u> Supplement to ECO # 2 R4 is a <u>75</u> ohm 1/8W resistor R4 is the 1st resistor from AA1			8	13-03064						
C 00004	6/70	C	D	.5	R2 is a <u>56</u> ohm 1/4W 5% resistor R2 is the 1st resistor above E2 E2 is a DEC transformer			4 4 1	10-00027 13-09995-0 16-09996-0						
00005	6/71		D		<u>NOTE:</u> See ECO # B6				Nil						
B 00006	4/71	D	D	.25	C3 is a <u>120</u> MMF 5% capacitor C3 is the closest capacitor from AA1			4	10-00018						
00007	06/77	E	D		<u>NOTE:</u> 1) PHASE IN DEC 7438 TO REPLACE 74H01-1 AT E5 2) CHANGES FCO #2 E5 IS A <u>DEC 7438</u> E5 IS THE LAST I.C. FROM AS1			1 OR 1	19-0949-00 19-11219-01 (SEE ECO #7)						

3103 MEMORY LEVELS & GATES				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
00001	1/70	A	A		NOTE: Print update				N/A						
C 00002	3/70	B	A	.5	E2 is a I.C. DEC 74H10 E2 is the 1st i.c. from AH1			3	19-09057						
00003	3/70		A		NOTE: Print update				N11						
C 00004	4/70	C	A	.25	R17 is a 500 ohm trim pot R17 is located in bottom left corner			1	13-05631						
C 00005	6/70	D	A	1.0	R1, R2 are 56 ohm, 1/4W, 5% resistors R1 & R2 are the two resistors just right of R4 R4 is the 10W resistor nearest the top right corner			2 2 1 2 1 1 1 1	13-02602 13-09994-0 13-00295 10-00027 11-09991 11-09990 16-09996-0 12-100001-0						
00006	2/71	E	A		NOTE: Print change				N11						
C 00007	1/72	F	A	.25	C11 is a .22 mfd 50V capacitor C11 is the only capacitor left of the two transistors at AC1			1	10-10274						

G225 X - Y CURRENT GENERATOR				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO	QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME			
C 00003	7/70	B	B	1.0	R22 is a <u>2.2K</u> 1/4W 5% resistor R22 is the 3rd resistor from bottom left corner	1	13-00417								
00004	7/70	C	C		R5 is a <u>680</u> ohm 1/4W 5% resistor R5 is the 1st resistor from AA1	4	12-02313 13-00347 13-00394								
00005	8/70	C			<u>NOTE:</u> Print change		Nil								
00006	9/70	D	D		<u>NOTE:</u> New etch rev		Nil								
C 00007	5/71	E	D	1.0	<u>NOTE:</u> Rework only "D" etch boards Insulating washers on all four heat sinks are tight and can not be rotated.	4	90-08493 90-08268 (thermal compound)								

G226 X - Y DECODER SWITCH				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CS	FROM ID	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDOS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL	DATE INSTALLED	CD	
00001	11/69	A	C		C22 is a .1ufd 50V capacitor C22 is below the two 1/4W resistors on board which are separated by a capacitor				N/A						
00002	3/70	B	C		NOTE: Documentation				Nil						
00003	3/70	C	C		Resistor closest to the bottom left corner is a 120 ohm 1/4W 5% resistor				N/A						
C 00004	11/71	D	D	0.5	C22 is a .22 ufd 50V capacitor C22 is below the two 1/4W resistors on board which are separated by a capacitor			1	10-10274						


M109		DEVICE SELECT		ETCH	OPTION	OPTION SERIAL#	PDP	SYSTEM SERIAL#	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
NONE					NOTE: NO ECO's										

M729 M11-E Control Logic				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
00001	03/70	A	B		NOTE: 1) New etch rev 2) Rework Etch "A" Revs E5 is aDEC I.C. 74 H 74				N/A						
B 00002	01/71	B	C	1.0	NOTE: 1) Must be installed in interleaved memories and optional for non-interleaved memory 2) Rework etch "B" rev only (ECO #3 has better rework instructions) No capacitor between the 270 OHM and 390 OHM resistors located near the upper left hand corner				NIL						
C 00003 6A 6B	06/72 01/73	C	C	1.5	NOTE: ECO# 3 contains ECO #2 & #3 rework instructions for all etch revs Measure an open CKT from E04-09 to E09-01 E09 is the 4th I.C. from AK1			1	19-05547	DZQGQ DZQCA DZQKB					

M1091 DEVICE SELECT					ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO				QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
C 00001	3/71	*	A	N/A	NOTE: MM11-E systems M1091 module if 16K of memory or more				1	M1091 etch "B" (if applicable)						
00002	3/71	A	B		NOTE: MM11-E, MM11-F and MMR11-E memory systems phase in M1091 modules. Check for M1091 module				1	M1091 Etch "B"						

M7290 CONTROL AND LOGIC				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE	TIME
00001	2/71	C	D		Jumper E06-06 to E31-10 feed through E6 is the 3rd I.C. from AL1 E31 is the last I.C. on board				Nil						
C 00002	9/71	D	E D C	2.0	NOTE: Rework "C" & "D" etch boards Jumper E03-03 to T07-10 feed through				Nil						
C 00003	8/72	E	F E D C	4.0	NOTE: 1) Must have ECO MM11-F-C0003 2) Rework all previous etch boards Jumper E02-08 to AC1				Nil	DZMMA thru DZMMI					
00004	1/77	F	F E D C		NOTE: DEC 74H01-1 DIRECT SUBSTITUTION TO DEC 7438 E IS A DEC 7438 E IS				NIL						

MM11-F





MM11-F
 4K 16 Bit
 22 Mil Memory

2398 R624
PROCESSOR TYPE PDP-11

MM11 0001 CODE DF ML A
MAR 7 PROBLEM Under some conditions when other options are placed along side an MM11-F they fail to operate correctly
CORRECTION Install a module protection plate
 In plant effectively All MM11-F as required
 Field effectively All MM11-F as required
 Time To Install And Test 10 Hours
 Kit Contents: PCB Prints And Parts

MM11 0002 CODE P MI B
APR 7 PROBLEM MM11-F Test Procedure needs updating
CORRECTION 1 Update Test Procedure
PROBLEM 2 MM11-FX print sets are the same as MM11-F
CORRECTION 2 (Recreate old MM11-FX Master Drawing at Los Yuma Master Drawing but format on MM11-F to include MM11-FX
 In plant effectively as documentation change only)

MM11 0003 CODE F MI D ML A
MAY 7 PROBLEM 1 Write signals and TVM have too much noise in them
CORRECTION 1 Install twisted pairs on write signals generate another EINH signal and use all twisted pairs on these signals
PROBLEM 2 RD-MEM - give bus too many loads on it
CORRECTION 2 Develop another RD-MEM signal to share the load
CORRECTION 3 Solve memory problems caused by DMA transfers that in some diagnostics don't show up. Also solves old obsolete G10 G10 problems.
 In plant effectively as required immediately
 Field effectively as required as MM11-F
 Time To Install And Test 10 Hours
 Kit Contents: PCB Prints

FECO'S



ENGINEERING
CHANGE ORDER 8524

ORIGINATOR Richard Manior 5-2
TEL EXT 2005 DATE 3/13/72
DISC PROJ NO 11 07602
COST CENTER NO 392
J.S.

ECO NO MM11F-0001
SHEET 1 OF 5
DATE RECEIVED 3-16-72
FIRST ISSUE 3-20-72
FINAL ISSUE

PROBLEM
Under some conditions when other options are placed along side an MM11/F they fail to operate correctly.

UNIT TO BE CHANGED
MM11/F
Memory
DISP CODE *

CORRECTION
Install a module protection plate.

OPTIONS AFFECTED
MM11/F

BREAK-IN/EFFECTIVITY
*Install module protection plate only when problems occur.

PRODUCT LINES AFFECTED
PDP11/20

ITEM NO	DOCUMENT/PART NO	OLD REV	NEW REV	DISP CODE	DESCRIPTION OF CHANGE	DOCUMENTATION AFFECTED	FIELD SERVICE AFFECTED	TYPE OF CHANGE
1.	A-PL-MM11-F-0	0	A	06	(Memory Assembly MM11/F) Change per this ECO.	<input type="checkbox"/> MODEL <input type="checkbox"/> DIAGNOSTICS <input type="checkbox"/> TECH MANUAL <input type="checkbox"/> TESTER <input type="checkbox"/> TEST PROG <input type="checkbox"/> TOGLING <input type="checkbox"/> PKG INST <input type="checkbox"/> ENG SPEC <input type="checkbox"/> PUNCH SPEC	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> Customer Charge <input type="checkbox"/> Product Line Change	<input type="checkbox"/> ELECTRICAL <input checked="" type="checkbox"/> MECHANICAL <input type="checkbox"/> MODULE ORDER PR MODEL <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
2.	7408490	-	-	07	(Module Protection Plate) Add quantity of 1 to drawing index.			
3.	A-ML-MM11-F	0	A	06	Update per item 1.			

- DISPOSITION CODES**
- 00 - RETURN TO STOCK
 - 01 - (DELETED)
 - 02 - USE PRESENT STOCK UNTIL NEW STOCK AVAILABLE (PHASE IN)
 - 03 - REWORK IMMEDIATELY (RETROFIT)
 - 04 - (DELETED)
 - 05 - (DELETED)
 - 06 - DOCUMENT CORRECTION
 - 07 - NEW ITEM (THIS ASSEMBLY)
 - 08 - NEW ITEM (OTHER COMPANY)
 - 09 - (DELETED)


APPROVAL SIGNATURES

Typ. nomen / Initial Signature
 DESIGN ENGR Pete Durant / [Signature]
 ENG MGR (OPT) _____
 FIELD SERVICE (OPT) _____
 CHIEF ENGR (MODULES ONLY) [Signature]

ECO MMIF
MMIF REWORK SHEET

SHEET 2 OF 3

1. LOOSEN 2 SCREWS AT POINTS A, CARE SHOULD BE USED AT ALL TIME SO THAT NO WIRES WILL BE DAMAGED.
2. SLIDE THE FINGERS OF THE MODULE PROTECTION PLATE UNDER THE END LUGS. THE PROTECTION PLATE SHOULD BE RIGHT AGAINST THE WIRED ASSY. FRAME, POINTS B.
3. TIGHTEN SCREWS.





FIELD CHANGE ORDER

FCO MM11F - D 0001
PAGE 1 OF 3

DATA PROCESSING AND DEC ECO LOG WILL POST THIS FCO WITH THE LEVEL OF URGENCY CODE REPLACING THE LEADING ZERO

FIELD EFFECTIVITY
MM11-F Memory Assembly

- LEVEL OF URGENCY CODE
- A MANDATORY HIGH PRIORITY
 - B MANDATORY
 - C HIGH PRIORITY IF SPECIFIC HARDWARE SOFTWARE, OR SYMPTOMS ARE PRESENT
 - D APPLICABLE IF SPECIFIC HARDWARE SOFTWARE, OR SYMPTOMS ARE PRESENT
 - E PRODUCT IMPROVEMENT OPTIONAL LOW PRIORITY

FIELD RETROFIT IS ANTICIPATED IN 5 % OF UNITS DEFINED ABOVE

- NO CHARGE TO CUSTOMER - ALL DEC INSTALLATION LABOR AND MATERIAL ARE TO BE REPORTED UNDER A "W" CHARGE CODE
- STANDARD APPLICABILITY - THIS FCO IS TO BE INSTALLED AT NO CHARGE FOR WARRANTY AND MAINTENANCE CONTRACT CUSTOMERS IN ACCORDANCE WITH THE TECHNICAL EFFECTIVITY ABOVE OTHERWISE AT CUSTOMER EXPENSE
- DOCUMENTATION 8 PARTS 8 DEC ON-SITE LABOR 8
- DEC'S MINIMUM BILLING APPLIES IF THIS FCO IS INSTALLED BY DEC THE DEC LABOR CHARGE ASSUMES FCO INSTALLATION DURING REGULAR WORKING HOURS IF INSTALLATION OUTSIDE OF REGULAR WORKING HOURS IS ORDERED DEC'S LATEST SCHEDULE OF HOURLY RATES WILL APPLY

DISCRETE PROJECT NUMBER (FOR FIELD SERVICE REPORTING)

AVAILABILITY DELAY	NO PARTS
PARTS <u>None</u>	

ESTIMATED DOWN TIME FOR INSTALLATION AND TESTING 1.0 HOURS

SPECIAL TEST EQUIPMENT TOOLS OR SUPPLIES

FIELD OFFICE FCO DISTRIBUTION CODE

- F IMMEDIATE FCO DISTRIBUTION TO ALL DEC FIELD OFFICES
- DF IMMEDIATE FCO DISTRIBUTION TO REGIONAL PRODUCT SUPPORT AND TO OFFICES WHERE SUBJECT EQUIPMENT IS LOCATED

LAST PREVIOUS FCO'S None

RELATED OR PREREQUISITE FCO'S

- FCO KIT DISTRIBUTION
- PSIC WILL INITIATE DISTRIBUTION OF FCO KITS AS DEFINED BELOW IN ACCORDANCE WITH THE EDP CONFIGURATION FILE
- ~~Field Installations - Orders should be placed for kits as defined below may be ordered as required~~

- MAINDEC CHANGE
- MAINTENANCE MANUAL CHANGE
- OPERATIONAL PROGRAMS AFFECTED

CONTENTS OF AN PSIC INITIATED KIT			
FIG	FCO	PRINTS	PARTS

PSIC INITIATED FCO KITS WILL BE DISTRIBUTED FOR ALL UNITS LISTED ON THE EDP CONFIGURATION FILE WITH THE FOLLOWING SERVICE STATUS CODES

D	H	A	B		
---	---	---	---	--	--

CONTENTS OF A FIELD OFFICE KIT			
FIG	FCO	PRINTS	PARTS
	X	X	X

- PRINT CHANGES ARE MINOR AND ARE TO BE MADE MANUALLY IN RED AND GREEN FCO REVISED PRINTS WILL BE SUPPLIED ONLY UPON SPECIAL REQUEST

VERIFICATION MATRICES

INSTALLATION AND TEST PROCEDURES

1. Carefully install module protection plate per FCO instructions. This requires insertion of the plate under existing wire runs which can be easily broken.

2. Run minires or other programs whose failure indicates the need for this FCO to be implemented. They should now function correctly.

PARTS REQUIRED

Q' 74-08490 Module Protection Plate

NOTES

FIELD SERVICE APPROVAL
Charles Dewey

ADK

3/20 7:20 3/21 7:20

THIS DOCUMENT WAS NOT PRODUCED FOR MICROFICHE; THEREFORE, ONLY PARTS OF IT ARE READABLE.

ENGINEERING
CHANGE ORDER # 4648

ORIGINATOR Richard Manion
TEL EXT 2005 DATE 5/10/72
DESC PROJ NO. 96 06122
COST CENTER NO. 392

ECO NO. MM11P-00003
SHEET 1 OF
DATE RECEIVED 5-12-72
FIRST ISSUE 5-18-72
FINAL ISSUE 7-4-72

PROBLEM

1. Strobe signals and TINH have too much noise on them.
2. Read H signal has too many loads on it.
3. Solves memory problems caused by DMA transfers that memory diagnostics don't show up, also, solves slot sensitive G103, G102 problems.

UNIT TO BE CHANGED
MM11/P
DISP CODE 03

CORRECTION

1. Install twisted pairs on strobe signals, generate another TINH signal and install twisted pairs on these signals.
2. Develop another Read H signal to share the load.

OPTIONS AFFECTED
MM11/P

BREAK-IN/EFFECTIVITY
All MM11/P's shipped after May 31 will have this ECO.
Rework M7290 module when necessary, all MM11/P's with this ECO have to have M7290's with ECO #1.

PRODUCT LINES AFFECTED
PDP11/15
PDP11/20
PDP11/45

ITEM NO	DOCUMENT/PART NO.	OLD REV	NEW REV	DISP CODE	DESCRIPTION OF CHANGE
1	K-WL-MM11-F-07	-	A	06	Update wire list.
2	A-PL-MM11-F-0	A	B	06	Update Rev. per this ECO.
3	A-ML-MM11-F	C	D	06	Update.
4	D-AD-7007263-0-0	-	A	06	Wire Ass'y MM11/F. See final release print.
5	D-BS-MM11-F-03	-	A	06	Core memory stack (2 sheets, See final release print.
6	A-PL-7007263-0-0	-	A	06	Update revision level.

DOCUMENTATION AFFECTED

- MODEL
- DIAGNOSTICS
- TECH MANUAL
- TESTER
- TEST PROG
- TOOLING
- PKG INST
- ENG SPEC
- PURCH SPEC

FIELD SERVICE AFFECTED

YES NO

Customer Charge

Product Line Change

TYPE OF CHANGE

- ELECTRICAL
- MECHANICAL
- MODULE

ORDER PR MODEL

YES

NO

DISPOSITION CODES

00 - RETURN TO STOCK
01 - (DELETED)
02 - USE PRESENT STOCK UNTIL NEW STOCK AVAILABLE (PHASE IN)
03 - REWORK IMMEDIATELY (RETROFIT)
04 - (DELETED)
05 - (DELETED)
06 - DOCUMENT CORRECTION
07 - NEW ITEM (THIS ASSEMBLY)
08 - NEW ITEM (THIS COMPANY)
09 - SCRAP IMMEDIATELY

APPROVAL SIGNATURES

Typewritten / Hand Signature

DESIGN ENGR Pete Durant / *Pete Durant*

ENGR MGR (OPT) _____

FIELD SERVICE (OPT) _____

CHIEF ENGR (MODULES ONLY) _____

ENGINEERING CHANGE ORDER
ADD/DELETE SHEET

ECO NO.
MM11F-00003
Sheet ___ of ___


WIRE LIST NO. K-WL-MM11-F-07

TITLE
MM11/F WIRE LIST
NEW REV. A


MAKE ALL DELETIONS FIRST WHEN INSTALLING

SIGNAL NAME	FROM PIN	TO PIN	COMPONENTS	ADD	DEL
TINH H	C01C1	D02E1			X
TINH H	D03E1	E03E1			X
TINH H	E01E1	F01E1			X
STROBE 00 H	C01R1	D02S1			X
STROBE 01 H	C01A1	E01S1			X
TSS H	F01V2	F01P1			X
TINH L	C01K1	F01S1		X	
TINH L	F01S1	F01U2		X	
TINH L	F01U2	F01V2		X	
TINH 00 H	C01C1	D02E1	WNT TWP	X	
GND	C01C2	D02C2	RED		X
TINH 01 H	F01T2	F01E1	WNT TWP	X	
GND	F01T1	F01C2	RED		X
TINH 01 H	F01T2	E02E1	WNT TWP	X	
GND	F01T1	E02C2	RED		X
STROBE 00 H	C01R1	D02S1	WNT TWP	X	
GND	C01T1	D02T1	RED		X
STROBE 01 H	C01A1	E01S1	WNT TWP	X	
GND	C01C2	E01T1	RED		X

466

	<h2 style="margin:0;">FIELD CHANGE ORDER</h2>	<p>FCO <u>MM11P-C 0003</u> PAGE <u>1</u> OF <u>1</u></p> <p>DATA PROCESSING AND DEC-ECO-LOS WILL POST THIS FCO WITH THE LEVEL OF URGENCY CODE REPLACING THE LEADING ZERO</p> <p>• LEVEL OF URGENCY CODE</p> <p>A MANDATORY HIGH PRIORITY B MANDATORY C HIGH PRIORITY IF SPECIFIC HARDWARE, SOFTWARE, OR SYMPTOMS ARE PRESENT D APPLICABLE IF SPECIFIC HARDWARE, SOFTWARE OR SYMPTOMS ARE PRESENT E PRODUCT IMPROVEMENT - OPTIONAL LOW PRIORITY</p> <p>CONCRETE PROJECT NUMBER (FOR FIELD SERVICE REPORTING)</p> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:50%;">AVAILABILITY DELAY</td> <td style="width:50%;">NO PARTS</td> </tr> <tr> <td>PARTS</td> <td style="text-align: center;">X</td> </tr> </table> <p>ESTIMATED DOWN TIME FOR INSTALLATION AND TESTING <u>1.0</u> HOURS</p> <p>SPECIAL TEST EQUIPMENT, TOOLS OR SUPPLIES</p> <p>LAST PREVIOUS FCO'S <u>D01</u></p> <p>RELATED OR PREREQUISITE FCO'S <u>M7290-00003</u></p> <p><input type="checkbox"/> MANDEC CHANGE <input type="checkbox"/> MAINTENANCE MANUAL CHANGE <input type="checkbox"/> OPERATIONAL PROGRAMS AFFECTED</p> <p>VERIFICATION MANDECS</p> <p>PARTS REQUIRED</p>	AVAILABILITY DELAY	NO PARTS	PARTS	X										
AVAILABILITY DELAY	NO PARTS															
PARTS	X															
<p>FIELD EFFECTIVITY</p> <p>Retrofit all MM11-F's</p>																
<p>FIELD RETROFIT IS ANTICIPATED IN <u>100</u> % OF UNITS DEFINED ABOVE</p>																
<p><input checked="" type="checkbox"/> NO CHARGE TO CUSTOMER ALL DEC INSTALLATION LABOR AND MATERIAL ARE TO BE REPORTED UNDER A "W" CHARGE CODE</p> <p><input type="checkbox"/> STANDARD APPLICABILITY THIS FCO IS TO BE INSTALLED AT NO CHARGE FOR WARRANTY AND MAINTENANCE CONTRACT CUSTOMERS IN ACCORDANCE WITH THE TECHNICAL EFFECTIVITY ABOVE OTHERWISE AT CUSTOMER EXPENSE</p> <p>DOCUMENTATION <u>0</u> PARTS <u>0</u> DEC ON-SITE LABOR <u>0</u></p> <p>DEC'S MINIMUM BILLING APPLIES IF THIS FCO IS INSTALLED BY DEC. THE DEC LABOR CHARGE ASSUMES FCO INSTALLATION DURING REGULAR WORKING HOURS. IF INSTALLATION OUTSIDE OF REGULAR WORKING HOURS IS ORDERED, DEC'S LATEST SCHEDULE OF HOURLY RATES WILL APPLY.</p>																
<p>FIELD OFFICE FCO DISTRIBUTION CODE</p> <p><input checked="" type="checkbox"/> F IMMEDIATE FCO DISTRIBUTION TO ALL DEC FIELD OFFICES <input type="checkbox"/> DF IMMEDIATE FCO DISTRIBUTION TO REGIONAL PRODUCT SUPPORT AND TC OFFICES WHERE SUBJECT EQUIPMENT IS LOCATED</p>																
<p>KIT DISTRIBUTION</p> <p><input type="checkbox"/> PSIC WILL INITIATE DISTRIBUTION OF FCO KITS AS DEFINED BELOW IN ACCORDANCE WITH THE EDP CONFIGURATION FILE</p> <p><input checked="" type="checkbox"/> PSIC WILL INITIATE DISTRIBUTION OF FCO KITS AS DEFINED BELOW IN ACCORDANCE WITH THE EDP CONFIGURATION FILE KITS AS DEFINED BELOW MAY BE ORDERED AS REQUIRED</p>																
<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td colspan="4" style="text-align: center;">CONTENTS OF AN PSIC INITIATED KIT</td> <td rowspan="2" style="font-size: small; vertical-align: top;">PSIC INITIATED FCO KITS WILL BE DISTRIBUTED FOR ALL UNITS LISTED ON THE EDP CONFIGURATION FILE WITH THE FOLLOWING SERVICE STATUS CODES</td> </tr> <tr> <td style="text-align: center;">P/S</td> <td style="text-align: center;">FCO</td> <td style="text-align: center;">PRINTS</td> <td style="text-align: center;">PARTS</td> </tr> <tr> <td style="text-align: center;"> </td> <td style="text-align: center;"> </td> <td style="text-align: center;"> </td> <td style="text-align: center;"> </td> <td style="text-align: center;">D H E W</td> </tr> </table>		CONTENTS OF AN PSIC INITIATED KIT				PSIC INITIATED FCO KITS WILL BE DISTRIBUTED FOR ALL UNITS LISTED ON THE EDP CONFIGURATION FILE WITH THE FOLLOWING SERVICE STATUS CODES	P/S	FCO	PRINTS	PARTS					D H E W	
CONTENTS OF AN PSIC INITIATED KIT				PSIC INITIATED FCO KITS WILL BE DISTRIBUTED FOR ALL UNITS LISTED ON THE EDP CONFIGURATION FILE WITH THE FOLLOWING SERVICE STATUS CODES												
P/S	FCO	PRINTS	PARTS													
				D H E W												
<p><input type="checkbox"/> PRINT CHANGES ARE MINIMAL AND ARE TO BE MADE MANUALLY IN RED AND GREEN. FCO REVISED PRINTS WILL BE SUPPLIED ONLY UPON SPECIAL REQUEST</p>																
<p>INSTALLATION AND TEST PROCEDURES</p>																
<p>NOTES</p> <p>Necessary to improve reliability on existing units.</p>																
<p>FIELD SERVICE APPROVAL</p> <p>Art Zins</p>		<p><u>24K</u> 5/16 5/17 (171) 5/15 400</p>														

THIS DOCUMENT WAS NOT PRODUCED FOR MICROFICHE, THEREFORE, ONLY PARTS OF IT ARE READABLE.



<p>VIỆT LẬP VI HÀNG CHỮ</p>	<p>CORE MEMORY STACK (X DRIVE)</p>	<p>D-05-MM11-F-03</p>	<p>A</p>
	<p>1. <i>Alyce Mustafa</i></p>	<p>8-7</p>	<p>GRAPHIC DESCRIPTION</p>


sho 3

WIRE TABLE

SIGNAL NAME	FROM PIN	TO PIN	COLOR	REMARKS	NAME SIGNAL	FROM PIN	TO PIN	COLOR	REMARKS
-15	A03L1	F04B2	↓ BLUE	WIRES MUST PHYSICALLY RUN TO THE RIGHT OF THE BLACK AND PINS					
TINN Ø Ø H GND	CP1C1 CP1C2	D02E1 D02C2	WHT BLK	TWP					
TINN Ø Ø H GND	F01T2 F01T1	F01F1 F01B2	WHT BLK	TWP	SA1B SA1B LNH1A	D04V1 D04V2 D04V2	ØØØ2 ØØØ2 ØØØ1	WHT BLK YEL	3 TWISTED WIRES
					STROBE Ø Ø GND	ØØØ1 ØØØ1	ØØØ1 ØØØ1	WHT BLK	TWP
					STROBE Ø Ø GND	ØØØ1 ØØØ2	ØØØ1 ØØØ1	WHT BLK	TWP

→ ADD

→ ADD

 <small>101 111 10 CHANGE ORDER</small>	WIRED ASSY M N 11-15 <i>W. J. JAMES</i>	DAD-707263-U-0	A
	GRAPHIC DESCRIPTION		

FGR

**MM11-F
4K 16 BIT 22 MIL MEMORY
FCO Cross Reference**

**A Chronological Listing of Field Retrofit FCO's Which Must Be
Considered in the Field Installation and Maintenance of This Option/Module/Power Supply**

• Indicates FCO Conjunction Must Be Considered With Prior FCO

- | | |
|--|--|
| <p>1 G102-B0002 MAR 70
G102-B0003
QUICK SYNOPSIS
8881 IC's replaced by higher speed 74H011 IC's
QUICK CHECK
74H011 IC's in place of 8881 IC's
NEW REVISION
Exchange with CS B or later</p> | <p>2 G225-C0003 JUL 70
QUICK SYNOPSIS
Speeds stabilization of X and Y current generator reference voltage
QUICK CHECK
R22 changed from 4.7K ohm to 2.2K ohms
NEW REVISION
Rework etch B to CS B</p> |
| <p>2 G103-C0002 MAR 70
QUICK SYNOPSIS
Increases system speed
QUICK CHECK
7410 IC replaced by 74H10
NEW REVISION
Rework etch B C to CS B</p> | <p>2 M930-C0001 AUG 70
QUICK SYNOPSIS
Power Fail requires BUS SP1 and BUS SP2 for AC LO and DC LO (In plant new etch B at CS A)
QUICK CHECK
R57 and R69 are 390 ohms
NEW REVISION
Exchange with etch B</p> |
| <p>3 G103-C0004 APR 70
QUICK SYNOPSIS
Provides new higher value trimpot
QUICK CHECK
R17 changed from 100 ohm to 500 ohm trimpot
NEW REVISION
Rework etch B C to CS C</p> | <p>• 5408475-C0006 OCT 70
QUICK SYNOPSIS
AC LO and DC LO return high after assertion in multiple box systems
QUICK CHECK
D003 clamping diode from AC LO (anode) and from DC LO to +5V line
NEW REVISION
Rework etch A B C to CS D</p> |
| <p>1 G102-B0004 JUN 70
QUICK SYNOPSIS
Decreases Turn off time of the 2007 transistors
QUICK CHECK
C2 C7 C12 C17 changed from 1000mmfd to 820mmfd
NEW REVISION
Rework etch D to CS D</p> | <p>2 M729-C0002 JAN 71
QUICK SYNOPSIS
Reduces memory cycle time on systems with 8K interleaved memory (In plant new etch C)
QUICK CHECK
Wire ADD E9 pin 2 to feed thru near E5 pin 1
NEW REVISION
Rework etch B to CS B</p> |
| <p>2 G103-C0005 JUN 70
QUICK SYNOPSIS
Provides increase to 6.84VDC for Sense amplifiers
QUICK CHECK
Heat sink ADDED to Q4 C1 and C2 changed from 1000mmfd to 820mmfd
NEW REVISION
Rework etch D E to CS D</p> | |

**MM11-F
4K 16 BIT 22 MIL MEMORY
FCO Cross Reference**

**A Chronological Listing of Field Retrofit FCO's Which Must Be
Considered in the Field Installation and Maintenance of This Option/Module/Power Supply**

• Indicates FCO Conjunction Must Be Considered With Prior FCO

- | | |
|---|---|
| <p>1 M1091-C0001 MAR 71
QUICK SYNOPSIS
Provides 1 unit load on BUS in systems with
16K or more memory
QUICK CHECK
M1091 replaces M109 module
NEW REVISION
Rework etch B to CS A</p> | <p>2 MM11F-C0003 MAY 72
QUICK SYNOPSIS
Reduces noise on TINH and strobe signals
QUICK CHECK
C01C1 to D02E1/C01C2 to D02C2
NEW REVISION
Rework to Wire List A</p> |
| <p>10 G102-B0006 APR 71
QUICK SYNOPSIS
Eliminates MM11 F's noise susceptibility
QUICK CHECK
C3 C8 C13 C18 changed from 33mmfd to
120mmfd
NEW REVISION
Rework etch D to CS D</p> | <p>11 M729-C0003 MAY 72
M729-D0004
QUICK SYNOPSIS
Unibus hangs with SSYN asserted from
memory
QUICK CHECK
Wire ADD E5 pin 6 to E3 pin 1
NEW REVISION
Rework etch B C to CS C</p> |
| <p>11 G225 C0007 MAY 71
QUICK SYNOPSIS
Prevent heat sink from shorting to etch
QUICK CHECK
Insulating washers under heat sinks</p> | <p>11 M7290-C0003 MAY 72
QUICK SYNOPSIS
Reduced inductance of TINH H etch corrects
noise condition (In plant new etch F)
QUICK CHECK
Wire ADD E11 pin 8 to feed thru going to
AR1
NEW REVISION
Rework etch C D to CS E</p> |
| <p>12 M7290-C0002 OCT 71
QUICK SYNOPSIS
Prevents Unibus hang with SSYN asserted
from memory (In plant new etch E)
QUICK CHECK
Wire ADD E8 pin 5 to E7 pin 9
NEW REVISION
Rework etch C to CS D</p> | |
| <p>13 MM11F-D0001 MAR 72
QUICK SYNOPSIS
Module protection plate prevents MM11 F
noise interaction with adjacent modules
QUICK CHECK
Presence of protection plate</p> | |

MM11-L

SECRET

MM11-L
8K 16 BIT 18 MIL MEMORY
FCO Cross Reference

A Chronological Listing of Field Retrofit FCO's Which Must Be
Considered in the Field Installation and Maintenance of This Option/Mod'le/Power Supply

• Indicates FCO Conjunction Must Be Considered With Prior FCO

- | | |
|--|--|
| <p>1 G110-B0004 MAY 72
QUICK SYNOPSIS
Corrects Delay line 3 termination on etch C
G110s
QUICK CHECK
R115 changed from 3 K ohms
NEW REVISION
Rework etch C to CS D
COMPATIBILITY
R115 changed from 3K ohms to 1K ohms</p> | <p>1 MM11-S-C0003 OCT 72
QUICK SYNOPSIS
Module protection plate prevents MM11 S
noise interaction with adjacent modules
QUICK CHECK
Presence of module protection plate</p> |
| <p>2 G110-B0005 MAY 72
QUICK SYNOPSIS
Corrects C152 insertion polarity (positive ter
minal) to +5V
QUICK CHECK
Positive terminal of C152 goes to +5V
NEW REVISION
Rework etch C D to CS E</p> | <p>1 G110-C0010 NOV 72
QUICK SYNOPSIS
Data errors occur during the first DATI to any
memory bank
QUICK CHECK
Wire ADD E28 pin 13 to E15 pin 10
NEW REVISION
Rework etch C D E to CS J</p> |
| <p>3 G231-B0001 MAY 72
QUICK SYNOPSIS
Prevents components on G231 shorting to
module above it
QUICK CHECK
Two phenolic 7/16" standoffs on module
NEW REVISION
Rework etch B to CS C</p> | <p>1 G110-D0012 DEC 72
QUICK SYNOPSIS
Provides print clarification affecting etch C
G110s
NEW REVISION
CS E5</p> |
| <p>1 G231-D0003 AUG 72
QUICK SYNOPSIS
Improves 15V and strobe margins when
operating at 55°C
QUICK CHECK
Sixteen D672 diodes replace 330 ohm
resistors
NEW REVISION
Rework etch B to CS F</p> | <p>1 G110-D0013 DEC 72
QUICK SYNOPSIS
Ensures PAL and PBL data bits gate high onto
the BUS
QUICK CHECK
Wire ADDs E40 pin 4 to pin 13 and E40 pin 9
to pin 12
NEW REVISION
Rework etch C to CS E6</p> |
| <p>1 G231-A0005 AUG 72
QUICK SYNOPSIS
Improves DC LO and AC LO circuit operation
QUICK CHECK
Wire ADD from R89 to R93
NEW REVISION
Rework etch C to CS E1</p> | <p>1 G231-D0009 DEC 72
QUICK SYNOPSIS
G231 prints redrawn to DEC standards
NEW REVISION
CS E4</p> |

**MM11-L
8K 16 BIT MIL MEMORY
FCO Cross Reference**

**A Chronological Listing of Field Retrofit FCO's Which Must Be
Considered in the Field Installation and Maintenance of This Option/Module/Power Supply**

• Indicates FCO Conjunction Must Be Considered With Prior FCO

- | | |
|--|--|
| <p>12 G109-C0004 DEC 72
QUICK SYNOPSIS
Replaces +3V with INIT L to reset STROBE one shot
QUICK CHECK
Wire ADD E28 pin 13 to E15 pin 10
NEW REVISION
Rework etch C. E to CS E3</p> | <p>11 G110-B0018 APR 73
QUICK SYNOPSIS
Eliminates noise on STROBE O H etch
QUICK CHECK
Twisted pair E32 pin 8 feed thru to E58 pin 4 feed thru/E33 pin 7 to ground side of C4
NEW REVISION
Rework etch C to CS E9</p> |
| <p>11 G110-C0015 MAR 73
QUICK SYNOPSIS
Allows longer memory cycle time on systems with high speed NPR devices
QUICK CHECK
DL3 changed from 100nsec to 125nsec delay
NEW REVISION
Rework etch C to CS E7</p> | <p>11 G109-C0010 JUL 73
QUICK SYNOPSIS
Eliminates noise induced condition where memory randomly picks up and drops bits
QUICK CHECK
E32 pin 8 feed thru to E58 pin 14 feed thru/E33 pin 7 to ground side of C44
NEW REVISION
Rework etch C to CS E7</p> |
| <p>13 G110-CD016
QUICK SYNOPSIS
Eliminates noise on BUS INIT etch
QUICK CHECK
Wire ADD's E4 pin 4 to E7 pin 7 AA1 feed thru to E7 pin 8
NEW REVISION
Rework etch C to CS E8</p> | <p>14 G110-C0019 NOV 73
QUICK SYNOPSIS
Widening R/W Reset L prevents memory skipping a restore cycle
QUICK CHECK
E26 pin 8 goes to tap 10 of Delay line
NEW REVISION
Rework etch C to CS E10</p> |
| <p>12 G109-C0006 MAR 73
QUICK SYNOPSIS
Lengthens memory cycle time
QUICK CHECK
DL3 replaced with 125nsec delay
NEW REVISION
Rework etch C to CS E4</p> | <p>14 G109 C0011 NOV 73
QUICK SYNOPSIS
Lengthens R/W flip flop reset input pulse to prevent skipped memory cycles on a read
QUICK CHECK
E26 pin 8 goes to top 10 of the Delay line
NEW REVISION
Rework etch C to CS E8</p> |
| <p>14 G109-C0007 MAR 73
QUICK SYNOPSIS
Eliminates noise coupling onto BUS INIT etch from data line etches
QUICK CHECK
Wire ADD E4 pin 4 to E7 pin 7
NEW REVISION
Rework etch C to CS E</p> | |

ECO
QUICK CHECK

NOV./74

MM11-L PARTS BREAKDOWN

G110	- Control and Data Loops
G231	- Memory Driver
H214	- 8K 16 Bit Memory Stack
MM11-L	- One 8K 16 Bit Bank of Memory

MM11-L FIELD CODED ECO'S

G110	B4, B5, C9, C10 & A, D12, D13 & A, C15 & A, C16, B18, C19
G231	B1, D3, A5, D9

March/75

MM11-L ECO PARTS

<u>NAME</u>	<u>ECO #</u>	<u>QTY</u>	<u>PART NUMBER</u>	<u>COMMENTS & DESCRIPTION</u>
G110	#4	1	13-00365	Resistor
	#5	1	10-05306	Capacitor
		4	90-08213	Standoffs
	#9	A/R	17-00024	#10 black/wire ground wire
	#10	1	19-05547	I.C.
	#15	1	16-11327	Delay
	#18	1	10-01610	Capacitor
G231	#1	2	90-06892	Standoffs
	#3	16	11-05275	Diode
	#15	A/R	90-09185	Jumper Wire

H11

G110 CONTROL & DATA LOOPS				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE 1 OF 4
---------------------------	--	--	--	------	--------	-----------------	-----	-----------------	----------	-----	-----	----------	------	-----	-------------

ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO	QTY.	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME
00001	03/72	A	C		R118 is a 220 ohm resistor R118 is left of E28 and right of DL3 or possibly under DL3 E28 is the 6th I.C. from BE1 DL3 is the small delay line right of DL1 DL1 is the biggest delay line		N11					
00002	03/72	B	C		DL3 is a 100n sec. delay line with part number D-10100 and/or 1609559 DL3 is a small delay line just right of DL1-08 DL1 is the biggest delay line on board DL3 CHANGED TO 125 N SEC. (P/N-322-1) AND/OR 1611327 BY ECO #15 +15A		N11					
00003	08/72	C	D		R113 is a 120 ohm 1/2W 5% resistor R113 is located at AS1 below DL2 DL2 is between E1 and E2		N11					
B 00004	08/72	D	C	1.0	NOTE: This ECO affects only "C" etch modules R115 is a 1K 1/2W 5% resistor R115 is the 3rd resistor right of DL1-12 DL1 is the biggest delay line	1	13-00365	DZMMG DZMMI				
B 00005	08/72	E	C	3.0	NOTE: This ECO affects only "C" etch modules C152 is a 6.8 ufd. capacitor with the cathode connected to the + etch on board. C152 is the capacitor right of DL1 -02 DL1 is the biggest delay line	1 4	10-05306 90-08213					

G110 CONTROL & DATA LOOPS		ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE
													2
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO	QTY.	PARTS REQUIRED	WAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CS NAME	
00006	11/72	F	E		R123 is a <u>390</u> ohm $\frac{1}{4}$ W 5% resistor R123 is the closest resistor to BS1		N11						
00007	09/72	E1	C		4 - Standoffs <u>screwed</u> on		N11						
00008	10/72	E2	C		C47 is a <u>.01</u> uf 100V 20% disc capacitor C47 is directly below E40 E40 is the 1st I.C. from CT1 DO NOT COUNT PULSE TRANSFORMER AS I.C.		N/A						
C 00009	12/72	E3	C	.5	Four #18 gauge black ground jumpers on SIDE ONE INSTEAD OF ON SIDE # TWO		17-00024 (#18 black & white teflon coated)						
C 00010 & 10A	11/72	E4	C	1.0	Jumper E15-10 to E28-13 E15 is the 4th I.C. from AV1. E28 is the 6th I.C. from BE1.	1	19-05547	DZQKB					
00011	12/72				<u>NOTE:</u> This ECO deleted		N/A						
D 00012	12/72	E5	C	N/A	<u>NOTE:</u> Print update affecting only "C" etch modules.		N11						

G110 CONTROL & DATA LOOPS		ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE
													3 OF 4
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO	QTY.	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
D 00013 & 13A	01/73	E6	C	.5	NOTE: Rework only "C" etch modules Jumper pin 4 to 13 on spare I.C. slot above E40 E40 is the 1st I.C. from CT1		N11	DZQMB					
00014	03/73	K	F		NOTE: This ECO affects only CS "F" etch "E" modules Jumper E15-10 to E28-13 E15 is the 4th I.C. from AV1 E28 is the 6th I.C. from BE1		N/A						
00014A	03/73	K	F		NOTE: This ECO affects E & F etch revs modules DL3 is 125 n sec. delay line with P/N 1-322-1 and or 1611327 DL3 is small delay line right of the big delay line		N/A						
C 00015 & 15A	05/73	E7	C	1.0	NOTE: This ECO affects "C" etch rev modules DL3 is 125 n sec. delay line with P/N L-00-01 and/or 1611327 DL3 is small delay line right of the big delay line	1	16-11327	DZMMG DZQKB DZQGA					
C 00016	06/73	E8	C	2.0	NOTE: Rework only "C" etch rev modules Jumper E04-04 to E07-07		N11	DZMMG DZQKB DZQGA					
00017	12/73	L	F		NOTE: This ECO affect only "E" & "F" etch rev modules Jumper E04-04 to E07-07		N11						

CONTROL & DATA LOOP		ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE
G110													4 OF 4
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO	QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
B 00018	10/73	E9	C	1.0	NOTE: Rework etch "C" Rev White wire of twisted pair from E32-06 feed through to E58-14 E32 is the 4th I.C from BS1 E58 is the 1st I.C from FC1	1	10-01610						
C 00019	12/73	E10	C	1.0	NOTE: Rework "C" etch rev Visual check of jumper or etch run from E26-08 to DL1 tap 10 (Do Not Use Meter) E26 is the 4th I.C from BE1 DL1 is the biggest delay line		NIL	DZQMB					
00020 6A	01/74	M	H		NOTE: Affects "F" etch rev Visual check of jumper or etch run from E26-08 to DL1 tap 10 (Do Not Use Meter) E26 is the 4th I.C from BE1 DL1 is the biggest delay line		N/A						
00021	07/74	N N E11 E11	H F E C		NOTE: Phase in DEC 8640's to replace DEC 380's		N/A						
00022	05/76	P	H		NOTE: DEC 7438 allowable I.C. substitution for 74H01-1 at E5, E18-E22		NIL						

G231 MEMORY DRIVER				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE 1 OF 3
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CB NAME	
B 00001	6/72	C	C	3.0	Two standoffs to prevent shorting			2	90-06892						
00002	8/72	D	D		Four standoffs on module				Nil						
D 00003	8/72	E	D	4.0	NOTE: Rework only "C" etch modules D116 is a D672 diode instead of being a resistor D116 is the only diode right of E1			16	11-05275	DZMMI					
00004 & 4A	8/72	F	E		E2 is a DEC I.C. 1074H00 E2 is the I.C. closest to the top left corner.				Nil						
A 00005	8/72	E1	C	4.0	NOTE: Rework only G231's with etch rev "C" which are in 11/05 and ME11 systems. 11/45 memories do <u>not</u> need this ECO Jumper from R101 to Q7 R101 is the 3rd resistor from bottom left corner Q7 is the biggest transistor from E1				Nil						
00006	8/72	E2	C		R170 is a 100 ohm 1/4W 5% resistor R170 is the 2nd resistor from top edge of board in the 1st row of resistors left of E1				Nil						
00007	9/72	E3	C		NOTE: Print update				Nil						

m11

G231 MEMORY DRIVER				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 2 OF 3
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CB NAME	
00008	9/72	E1A E2A E3A	C C C		C52 is a 470 pfd 100V 5% capacitor C52 is at the far left of DR1 and the only component between two transistors				Nil						
D 00009	12/12	E4	C	N/A	NOTE: Field service clarification for etch "C" modules				Nil						
00010	3/73	H	E		E1 is a DEC I.C. 4011 quad transistor				N/A						
00011	4/73	E5	C		E1 is a DEC I.C. 4011 quad transistor				N/A						
00012	4/73	J	E		NOTE: Affects etch "E" rev only R176 is a 4.7K 1/4W 5% resistor R176 is the 1st resistor below two transistors at the far left of EJ1				N/A						
00013	11/73	K	E		NOTE: I.C. substitution cancelled by ECO # 16				N/A						
00014	2/74	L	E		Q12 as snap-on heat sink Q12 is closest transistor to bottom left corner.				N/A						
00015	6/74	M	E ALL		NOTE: This ECO affects all etch rev modules. J1 & J2 have insulated jumper wire J1 & J2 are between E31 and E34 E31 is the last I.C. from CD slot				N/A						
00016	/74	N E6	E C		NOTE: I.C. 380 and 7380 are unsuitable E9, E15, E16, E17 are I.C. DEC 8640's E9 is the last I.C. from AV1 E15 is the 1st I.C. from BF1				N/A						

G231 MEMORY DRIVER				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYG. UNIT	SLOT	IPB
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY.	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME
00017	01/75	P	E		Q6 is a DEC 6534C transistor Q6 is the <u>last</u> transistor from EJ1				N/A					
00018	04/75	R	E		<u>NOTE:</u> Phase in jumper wire For current loops using teflon insulated wire				N/A					

REVISION DATE MAR/77

H214 - 8K x 16 BIT MEMORY STACK				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CS	FROM	ECO MFS. FROM	QUICK CHECK CAUTION - NOT COMPLETE ECO	QTY	PARTS REQUIRED	INDEXES REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL	DATE INSTALLED	CS NO.			
00001	6/72	B			<u>NOTE:</u> Print change		Nil								
00002	1/73	C			<u>NOTE:</u> Reference chart for H214, H215, H216 and G645 etch & CS revs		Nil								
00003	6/73	D			<u>NOTE:</u> Allowable I.C. substitution is DEC 2501 to DEC 2501-01, 2501-02, 2501-03		N/A								
00004	10/73	E			<u>NOTE:</u> Print correction		Nil								
00005	11/73	F			<u>NOTE:</u> Print correction		Nil								
00006	07/74	H			<u>NOTE:</u> Documentation update		Nil								
00007 SA	12/74	J			<u>NOTE:</u> DOCUMENTATION FOR AMPLE STACK		Nil								

H214 - 8K x 16 BIT MEMORY STACK				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE 1 OF 1
---------------------------------	--	--	--	------	--------	-----------------	-----	-----------------	----------	-----	-----	----------	------	-----	-------------

ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO	QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME
00001	6/72	B			<u>NOTE:</u> Print change		Nil					
00002	1/73	C			<u>NOTE:</u> Reference chart for H214, H215, H216 and G645 etch & CS revs		Nil					
00003	6/73	D			<u>NOTE:</u> Allowable I.C. substitution is DEC 2501 to DEC 2501-01, 2501-02, 2501-03		N/A					
00004	10/73	E			<u>NOTE:</u> Print correction		Nil					
00005	11/73	F			<u>NOTE:</u> Print correction		Nil					
00006	/74	H			<u>NOTE:</u> Documentation update							

MMF 1 1 - LP

FCR

MM11-LP
8K 16 BIT PARITY (18 BIT) MEMORY MODULE SET
FCO Cross Reference

A Chronological Listing of Field Retrofit FCO's Which Must Be
Considered in the Field Installation and Maintenance of This Option/Module/Power Supply

• Indicates FCO Conjunction Must Be Considered With Prior FCO

- | | |
|--|---|
| <p>1 G231-B0001 MAY 72
QUICK SYNOPSIS
Prevents components on G231 shorting to module above it
QUICK CHECK
Two phenolic 7/16 standoffs on module
NEW REVISION
Rework etch B to CS C</p> | <p>1 G109-C0007 MAR 73
QUICK SYNOPSIS
Eliminates noise coupling onto BUS INIT etch from data line etches
QUICK CHECK
Wire ADD E4 pin 4 to E7 pin 7
NEW REVISION
Rework etch C to CS E</p> |
| <p>2 G231-D0003 AUG 72
QUICK SYNOPSIS
Improves 15V and strobe margins when operating at 55° C
QUICK CHECK
Sixteen D672 diodes replace 330 ohm resistors
NEW REVISION
Rework etch B to CS F</p> | <p>2 C109-C0010 JUL 73
QUICK SYNOPSIS
Eliminates noise induced condition where memory randomly picks up and drops bits
QUICK CHECK
Twisted pair E32 pin 6 feed thru to E58 pin 14 feed thru E33 pin 7 to ground side of C44
NEW REVISION
Rework etch C to CS E7</p> |
| <p>1 G231-A0005 AUG 72
QUICK SYNOPSIS
Improves AC LO and DC LO circuit operation
QUICK CHECK
Wire ADD from R89 to R93
NEW REVISION
Rework etch C to CS E1</p> | <p>2 G109-C0011 NOV 73
QUICK SYNOPSIS
Lengthens RW flip flop reset input pulse to prevent skipped memory cycles on a read
QUICK CHECK
E26 pin 8 goes to top of 10 of the Delay line
NEW REVISION
Rework etch C to CS E8</p> |
| <p>1 G231-D0009 DEC 72
QUICK SYNOPSIS
G231 prints redrawn to DEC standards
NEW REVISION
CS E4</p> | <p>2 G109-C0004 DEC 74
QUICK SYNOPSIS
Replaces +3V with INIT L to reset STROBE one shot
QUICK CHECK
Wire ADD E28 pin 13 to E15 pin 10
NEW REVISION
Rework etch C E to CS E3</p> |
| <p>1 G109-C0006 MAR 73
QUICK SYNOPSIS
Lengthens memory cycle time
QUICK CHECK
DL3 replaced with 125 nsec delay
NEW REVISION
Rework etch C to CS E4</p> | |

ECO
QUICK CHECK

NOV./74

MM11-LP PARTS BREAKDOWN

G109	- Control & Data Loops
G231	- Memory Driver
H215	- 8K 16 Bit Memory Stack
MM11-LP	- One 8K Parity Memory Bank

450 1

MAR/76

MM11-LP FIELD CODED ECO'S

G109

- C4, C6, C7, C10, C11

G231

- B1, D3, A5, D9

JAN./75

MM11-LP ECO PARTS

<u>NAME</u>	<u>ECO #</u>	<u>QTY</u>	<u>PART NUMBER</u>	<u>COMMENTS & DESCRIPTION</u>
G109	# 3, 3A	8	10-00064	Capacitor
		4	10-01610	Capacitor
		1	13-00309	Capacitor
		5	13-05324	Resistor
G109	# 6	1	16-11327	Delay
G109	# 10	1	10-01610	Capacitor
		A/R	91-07720-09	White Wire
G231	# 1	2	90-06892	Standoffs
G231	# 3	16	11-05275	Diode
G231	# 15	A/R	90-09185	Jumper Wire
M7259	# 4	1	13-01874	Resistor
		1	13-09143-11	Resistor

G109 CONTROL & DATA LOOPS		ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 1 OF 3
ECC	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO		QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAM
00001	12/72	F	E		NOTE: New etch Rev			NIL					
00002 &A	12/72	E1	C		Standoffs are screwed on			N/A					
00003 &A	01/73	E2	C		C47 is a .01uf , 100V 20% disc capacitor C47 is directly below E40 E40 is the 1st I.C. from CT1 NOTE: DO NOT COUNT PULSE TRANSFORMER		8 4 1 5	10-000064 10-01610 13-00309 13-05324					
C 00004	01/73	E3	C	2.0	NOTE: Rework G109-YA only for parity memory Jumper from E15-10 to E28-13 E15 is the 4th I.C. from AV1 E28 is the 6th I.C. from BE1			NIL	DZMFA				
00005	05/73	K	F		NOTE: Affects etch "E" and "F" revs DL3 is 125 n sec. delay line with part number L-00-01 and/or 16-11327 DL3 is the small delay line left of E28 E28 is the 6th I.C. from BE1			NIL					
C 00006	05/73	E4	C	1.0	NOTE: Affects etch "C" revs DL3 is a 125 n sec. delay line part number L-00-01 and/or 16-11327 DL3 is a small delay line left of E28 E28 is the 6th I.C. from BE1		1	16-11327	DZMFC DZQMB				

G109 CONTROL & DATA LOOPS				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 2 OF 3
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED	CE NA	
C 00007	05/73	E5	C	1.0	NOTE: Affects etch "C" rev G109 & G109-YA modules Jumper E04-04 to E07-07				NIL	DZQKB					
00008 &A	06/75	E6	C		NOTE: 1) Affects etch "C" revs. 2) Generate separate G109-YA documentation 3) Change component substitution list R96 is a 82 ohm 1/4W 5% resistor R96 is right of E44 E44 is the 2nd I.C. left of DA1				NIL						
00009	12/73	L	F		NOTE: Affects etch "E" & "F" rev - G109 and G109-YA. Jumper E04-04 to E07-07			1	10-01610						
C 00010	12/73	E7	C	1.0	NOTE: Affects etch "C" rev White jumper from E32-06 to E58-14 E32 is the 4th I.C. from BS1 E58 is the 1st I.C. from FC1			1 A/R	10-01610 91-07720-09						
C 00011	12/73	E8	C	1.0	NOTE: Rework etch "C" rev Jumper or etch run from E26-08 to tap 10 of DL1 E26 is the 4th I.C. from BE1 DL1 is the biggest delay line				NIL	DZQMB					
00012 &A	06/74	M	H		NOTE: Affects etch "F" rev Jumper E26-08 to DL1-10 E26 is the 3rd I.C. from BE1 DL1 is the biggest delay line				N/A						

G109 CONTROL & DATA LOOPS		ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 3 OF 3
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO		QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAM
00013	07/74	E9	C		NOTE: Phase in DEC 8640 to replace DEC 380 and DEC 7380 chips.		8	19-11469					
00014	05/76	P	H		NOTE: DEC 7438 allowable I.C. substitution for 74H01-1 at E5, E18 to E22.			NIL					

G231 MEMORY DRIVER				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 1 OF 3
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE	
B 00001	6/72	C	C	3.0	Two standoffs to prevent shorting			2	90-06892						
00002	8/72	D	D		Four standoffs on module				Nil						
D 00003	8/72	E	D	4.0	NOTE: Rework only "C" etch modules D116 is a D672 diode instead of being a resistor D116 is the only diode right of E1			16	11-05275	DZMMI					
00004 & 4A	8/72	F	E		E2 is a DEC I.C. 1074H00 E2 is the I.C. closest to the top left corner.				Nil						
A 00005	8/72	E1	C	4.0	NOTE: Rework only G231's with etch rev "C" which are in 11/05 and ME11 systems. 11/45 memories do <u>not</u> need this ECO Jumper from R101 to Q7 R101 is the 3rd resistor from bottom left corner Q7 is the biggest transistor from E1				Nil						
00006	8/72	E2	C		R170 is a 100 ohm 1/4W 5% resistor R170 is the 2nd resistor from top edge of board in the 1st row of resistors left of E1				Nil						
00007	9/72	E3	C		NOTE: Print update				Nil						

G231 MEMORY DRIVER				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 2 OF 3
ECO	RELEASE DATE	CS	ETCH #	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
00008	9/72	E1A E2A E3A	C C C		C52 is a 470 pfd 100V 5% capacitor C52 is at the far left of DR1 and the only component between two transistors				Nil						
D 00009	12/12	E4	C	N/A	NOTE: Field service clarification for etch "C" modules				Nil						
00010	3/73	H	E		E1 is a DEC I.C. 4011 quad transistor				N/A						
00011	4/73	E5	C		E1 is a DEC I.C. 4011 quad transistor				N/A						
00012	4/73	J	E		NOTE: Affects etch "E" rev only R176 is a 4.7K 1/4W 5% resistor R176 is the 1st resistor below two transistors at the far left of EJ1				N/A						
00013	11/73	K	E		NOTE: I.C. substitution cancelled by ECO # 16				N/A						
00014	2/74	L	E		Q12 as snap-on heat sink Q12 is closest transistor to bottom left corner.				N/A						
00015	6/74	M	E ALL		NOTE: This ECO affects all etch rev modules. J1 & J2 have insulated jumper wire J1 & J2 are between E31 and E34 E31 is the last I.C. from CD slot				N/A						
00016	/74	N E6	E C		NOTE: I.C. 380 and 7380 are unsuitable E9, E15, E16, E17 are I.C. DEC 8640's E9 is the last I.C. from AV1 E15 is the 1st I.C. from BF1				N/A						

G231 MEMORY DRIVER				ETCH	OPTION	OPTION SERIAL #	PD?	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 3 OF 3
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO	QTY.	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CB NAME			
00017	01/75	P	E		Q6 is a <u>DMC 6L34C</u> transistor Q6 is the <u>last</u> transistor from EJ1		N/A								
00018	04/75	R	E		<u>NOTE:</u> Phase in jumper wire For current loops using teflon insulated wire		N/A								

REVISION DATE MAR/77

H215 8K x 18 BIT MEMORY STACK				ETCH	OPTION	OPTION SPEC. #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CC	ITEM #	ECO MFG. DATE	CHECK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	HANDNESS REQUIRED	PRINT SET	ACTUAL INSTALL	DATE	BY	REMARKS
00101	7/73	A			NOTE: Print change										
01012 62	12/74				NOTE: DO NOT INSTALL FOR AMPER STACK										


A1401

MM11-S

NOV/74

MM11-S PARTS BREAKDOWN

7008816	-Backplane Assembly
7008855-2B	-11/45 MM11 Power Cable (old)
7008909	-11/40 MM11 Power Cable (old)
7009562	-G772 System Unit Harness (new)
G110	-Control & Data Loops
G231	-Memory Drivers
H214	-8K Bank of Core Memory
BC11-A	-Unibus Cable
M920	-Unibus Jumper
MM11-S	-Single Backplane Unit



DIY


FECOS

ENGINEERING CHANGE ORDER		ORIGINATOR R. Manion 1-3 TEL EXT 2005 DATE 10/16/72 DBC PROJ NO 876A 06314 COST CENTER NO 392 W.O. 1732		ECO NO. MM11-00003 SHEET <u>1</u> OF <u>2</u> DATE RECEIVED 10-17-72 FIRST ISSUE 10-19-72 FINAL ISSUE 11-14-72		
PROBLEM Under some conditions when other options are placed along side an MM11/S they fail to operate correctly.				UNIT TO BE CHANGED MM11/S MEMORY DBC CODE *02 OPTIONS AFFECTED MM11/S MM11/SP		
CORRECTION Install a module protection plate.				PRODUCT LINES AFFECTED PDP11/45		
BREAK-IN/EFFECTIVITY *Install on all units in production. Install in field if required.						
ITEM NO	DOCUMENT/PART NO	OLD REV	NEW REV	DBC CODE	DESCRIPTION OF CHANGE	AFFECTED
1.	B-DD-MM11-S	A	B	06	(Drawing Directory) Change per this ECO. (Module Protection Plate) Add B-MB-7408490-00 to drawing directory.	DOCUMENTATION AFFECTED <input type="checkbox"/> MODEL <input type="checkbox"/> DIAGNOSTICS <input type="checkbox"/> TECH MANUAL <input type="checkbox"/> TESTER <input type="checkbox"/> TEST PROG <input type="checkbox"/> TOOLING <input type="checkbox"/> PKG INST <input type="checkbox"/> EMU SPEC <input type="checkbox"/> PURCH SPEC FIELD SERVICE AFFECTED <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> Customer Charge <input checked="" type="checkbox"/> Product Line Charge TYPE OF CHANGE <input type="checkbox"/> ELECTRICAL <input checked="" type="checkbox"/> MECHANICAL <input type="checkbox"/> MODULE ORDER PR MODEL <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
DISPOSITION CODES 00 - RETURN TO STOCK 01 - (DELETED) 02 - USE PRESENT STOCK UNTIL NEW STOCK AVAILABLE (PHASE IN) 03 - REWORK IMMEDIATELY (RETROFIT) 04 - (DELETED) 05 - (DELETED) 06 - DOCUMENT CORRECTION 07 - NEW ITEM (THIS ASSEMBLY) 08 - NEW ITEM (THIS COMPANY) 09 - SCRAP IMMEDIATELY				APPROVAL SIGNATURES <div style="text-align: center;"> 1-3 Typewritten Hand Signature DESIGN ENGR <u>Pete Durant</u> <i>Pete Durant</i> ENG MGR (OPT) _____ FIELD SERVICE (OPT) _____ CHIEF ENGR (MODULES ONLY) _____ </div>		

614

MM115 REWORK SHEET

1. LOOSEN 2 SCREWS AT POINTS A. CARE SHOULD BE USED AT ALL TIME SO THAT NO WIRES ARE DAMAGED.
2. SLIDE THE FINGERS OF THE MODULE PROTECTION PLATE UNDER THE GND LUGS. THE PROTECTION PLATE SHOULD BE RIGHT AGAINST THE WIRED ASSY. FRAME, POINT B.
3. TIGHTEN SCREWS.



MMNS-00003
Sheet 2 of 2



FIELD CHANGE ORDER

FCO MM1S - C 0003
PAGE 1 OF 1

DATA PROCESSING AND DEC FIELD OFFICE WILL POST THIS FCO WITH THE LEVEL OF URGENCY CODE REPLACING THE LEADING ZERO

FIELD INITIATIVE
Retrofit all MM1-S memories as required

- LEVEL OF URGENCY CODE**
- A MANDATORY HIGH PRIORITY
 - B MANDATORY
 - C HIGH PRIORITY IF SPECIFIC HARDWARE SOFTWARE OR SYMPTOMS ARE PRESENT
 - D APPLICABLE IF SPECIFIC HARDWARE SOFTWARE OR SYMPTOMS ARE PRESENT
 - E PRODUCT IMPROVEMENT (OPTIONAL) LOW PRIORITY

FIELD RETROFIT IS ANTICIPATED IN _____ % OF UNITS DEFINED ABOVE

NO CHARGE SYSTEMS ALL DEL. INSTALLATION LABOR AND MATERIAL ARE TO BE REPORTED UNDER A "W" CHARGE CODE

STANDARD APPLICABILITY THIS FCO IS TO BE INSTALLED AT NO CHARGE FOR WARRANTY AND MAINTENANCE CONTRACT CUSTOMERS IN ACCORDANCE WITH THE TECHNICAL EFFECTIVITY ABOVE OTHERWISE AT CUSTOMER EXPENSE

DOCUMENTATION S _____ PARTS S _____ DEC. SITE LABOR S _____

DEC'S MINIMUM BILLING APPLIES IF THIS FCO IS INSTALLED BY DEC. THE DEL. LABOR CHARGE ASSUMES FCO INSTALLATION DURING REGULAR WORKING HOURS. IF INSTALLATION OUTSIDE OF REGULAR WORKING HOURS IS ORDERED DEC'S LATEST SCHEDULE OF HOURLY RATES WILL APPLY.

DEC OR FI PRODUCT NUMBER
FOR FIELD SERVICE REPORTING: **W67**

AVAILABILITY DELAY **None** NO PARTS

ESTIMATED DOWN TIME FOR INSTALLATION AND TESTING **0.5 HOURS**

SPECIAL TEST EQUIPMENT TOOLS OR SUPPLIES

FIELD (OFFICE) FCO DISTRIBUTION CODE

F IMMEDIATE FCO DISTRIBUTION TO ALL DEC FIELD OFFICES
 IF IMMEDIATE FCO DISTRIBUTION TO REGIONAL PRODUCT SUPPORT

LAST PREVIOUS EFFECTIVE **None**

RELATED PREREQUISITE FCO'S

FIELD INITIATIVE

NOTES AS DEFINED BELOW MAY BE ORDERED AS REQUIRED

- MAINTENANCE CHANGE
- MAINTENANCE MANUAL CHANGE
- OPERATIONAL PROGRAMS AFFECTED

CONTENTS OF AN FSI INITIATED FCO

FCO	FCO	PARTS	PARTS

FCO INITIATED FCO'S WILL BE DISTRIBUTED FOR ALL UNITS LISTED ON THE TOP CONFIGURATION FILE WITH THE FOLLOWING SERVICE STATUS CODES

CONTENTS OF A FIELD ORDERED FCO

FCO	FCO	PARTS	PARTS
	X	X	X

D	H	A	W
---	---	---	---

VERIFICATION CODES

11-DZQMB

INSTALLATION AND TEST PREPARED BY

PARTS REQUIRED
Q1 74-08490 Module protection plate

NOTES This FCO is required when other options such as KW1-P, etc. are physically mounted next to an MM1-S memory. Noise generated by the MM1-S may interact with adjacent modules.

FIELD SERVICE APPROVAL

Art Zins

Art Zins

10/30 450

THIS DOCUMENT WAS NOT PRODUCED FOR MICROFICHE; THEREFORE, ONLY PARTS OF IT ARE READABLE.

FOR

314

MM11-8
8K, 16 BIT 18 MIL MEMORY
FCO Cross Reference

A Chronological Listing of Field Retrofit FCO's Which Must Be Considered in the Field Installation and Maintenance of This Option/Module/Power Supply

• Indicates FCO Conjunction Must Be Considered With Prior FCO

- | | |
|---|--|
| <p>■ G231-B0001 MAY 71
QUICK SYNOPSIS
Prevents components on G231 shorting to module above it
QUICK CHECK
Two phenolic 7/16" standoffs on module
NEW REVISION
Rework etch B to CS C</p> | <p>■ G231-A0005 AUG 72
QUICK SYNOPSIS
Improves AC LO and DC LO circuit operation
QUICK CHECK
Wire ADD from R89 to R93
NEW REVISION
Rework etch C to CS E1</p> |
| <p>■ G110-B0004 MAY 72
QUICK SYNOPSIS
Corrects delay line 3 termination on C etch G110's
QUICK CHECK
R115 changed from 3K to 1K ohm
NEW REVISION
Rework etch C to CS D</p> | <p>■ G110-D0012 DEC 72
QUICK SYNOPSIS
Provides print clarification affecting etch C G110's
NEW REVISION
CS E5</p> |
| <p>■ G110-B0005 MAY 72
QUICK SYNOPSIS
Corrects C152 insertion polarity (positive terminal) to +5V
QUICK CHECK
Positive terminal of C152 goes to +5V
NEW REVISION
Rework etch C, D to CS E</p> | <p>■ G110-D0013 DEC 72
QUICK SYNOPSIS
Ensures PAL and PBL data bits gate high onto the Bus
QUICK CHECK
Wire ADD's E40 pin 4 to pin 13 and E40 pin 9 to pin 12
NEW REVISION
Rework etch C to CS E6</p> |
| <p>■ G231-D0003 AUG 72
QUICK SYNOPSIS
Improves 15V and strobe margins when operating at 55°C
QUICK CHECK
Sixteen D672 diodes replace 330 ohm resistors
NEW REVISION
Rework etch B to CS F</p> | <p>■ G110-C0015 MAR 73
QUICK SYNOPSIS
Allows longer memory cycle time on systems with high speed NPR devices
QUICK CHECK
DL3 changed from 100nsec to 125nsec delay
NEW REVISION
Rework etch C to CS E7</p> |
| | <p>■ G110-C0016 MAR 73
QUICK SYNOPSIS
Eliminates noise on BUS INIT etch
QUICK CHECK
Wire ADD S E4 pin 4 to E7 pin 7 AA1 feed thru to E7 pin 6
NEW REVISION
Rework etch C to CS E8</p> |

MM11-S
8K, 18 BIT 18 MIL MEMORY
FCO Cross Reference

**A Chronological Listing of Field Retrofit FCO's Which Must Be
Considered in the Field Installation and Maintenance of This Option/Module/Power Supply**

• Indicates FCO Conjunction Must Be Considered With Prior FCO

G110-B0018 APR 73

QUICK SYNOPSIS

Eliminates noise on STROBE O H etch

QUICK CHECK

E32 pin 8 feed thru to E58 pin 4 feed
thru/E33 pin 7 to ground side of C44

NEW REVISION

Rework etch C to CS E9

G110-C0019 NOV 73

QUICK SYNOPSIS

Lengthening R/W RESET L prevents memory
slipping a Restore cycle

QUICK CHECK

E28 pin 8 goes to Tap 10 of Delay line

NEW REVISION

Rework etch C to CS E10

MM11S C0003 OCT 73


QUICK SYNOPSIS

Module protection plate eliminates MM11 S
noise interaction with adjacent modules

QUICK CHECK

Presence of protection plate

ECO
QUICK CHECK



my

NOV/74

MM11-S PARTS BREAKDOWN

7008816	-Backplane Assembly
7008855-2B	-11/45 MM11 Power Cable (old)
7008909	-11/40 MM11 Power Cable (old)
7009562	-G772 System Unit Harness (new)
G110	-Control & Data Loops
G231	-Memory Drivers
H214	-8K Bank of Core Memory
BC11-A	-Unibus Cable
M920	-Unibus Jumper
MM11-S	-Single Backplane Unit

JAN/75

MM11-S ECO PARTS

<u>NAME</u>	<u>ECO #</u>	<u>QTY</u>	<u>PART NUMBER</u>	<u>COMMENTS & DESCRIPTION</u>
G110	# 4	1	13-00365	Resistor
	# 5	1	10-05306	Capacitor
		4	90-08213	Standoffs
	# 9	A/R	17-00024	# 10 black/white gd.wire
	#10	1	19-05547	I.C.
	#15	1	16-11327	Delay
	#18	1	10-01610	Capacitor
G231	# 1	2	90-06892	Standoffs
	# 3	16	11-05275	Diode
	#15	A/R	90-09185	Jumper wire
MM11-S	# 3	1	74-08490	Shield

JAN./75

MM11-S FIELD CODED ECO'S

G110	B4, B5, C9, C10 & A, D12, D13 & A, C15 & A, C16, B18, C19
G231	B1, D3, A5, D9
MM11-S	C3

CS

MM11-S 8K 16 BIT MEMORY				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CS	ETCH #	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO				QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CD NAME
00001	4/72		A		Jumper A01-U1 to A02-U1					Nil					
00002	9/72				<u>NOTE:</u> Print change					Nil					
C 00003	10/72			.5	A module protection plate beside MM11-S memory bank.				1	74-08490					
00004	11/72				<u>NOTE:</u> Adds test procedures for MM11-K, L, M, S and SP modules and systems					Nil					
00005	10/73				Jumper C02-A2 to F01-A2					Nil					
00006	2/74				<u>NOTE:</u> New harness (7009562) introduced for 15 pin power distribution. 11/40 and 11/45 with serial numbers greater than 6000 and 2000 respectively have a G772 system unit harness					N/A					
00007	05/75				<u>NOTE:</u> Document update					NIL					
00008	05/76				<u>NOTE:</u> Documentation update					NIL					

G110 CONTROL & DATA LOOPS		ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE
													1 OF 4
ECO	RELEASE DATE	CS	ETCH #	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO	QTY.	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
00001	03/72	A	C		R118 is a 220 ohm resistor R118 is left of E28 and right of DL3 or possibly under DL3 E28 is the 6th I.C. from BE1 DL3 is the small delay line right of DL1 DL1 is the biggest delay line		N11						
00002	03/72	B	C		DL3 is a 100n sec. delay line with part number D-10100 and/or 1609559 DL3 is a small delay line just right of DL1-08 DL1 is the biggest delay line on board DL3 CHANGED TO 125 N SEC. (P/N-322-1) <u>AND/OR 1611327 BY ECO #12 +15A</u>		N11						
00003	08/72	C	D		R113 is a 120 ohm 1/2W 5% resistor R113 is located at AS1 below DL2 DL2 is between E1 and E2		N11						
E 00004	08/72	D	C	1.0	<u>NOTE:</u> This ECO affects only "C" etch modules R115 is a 1K 1/2W 5% resistor R115 is the 3rd resistor right of DL1-12 DL1 is the biggest delay line	1	13-00365					DZMMG DZMMI	
B 00005	08/72	E	C	3.0	<u>NOTE:</u> This ECO affects only "C" etch modules C152 is a 6.8 ufd. capacitor with the cathode connected to the + etch on board. C152 is the capacitor right of DL1 -02 DL1 is the biggest delay line	1 4	10-05306 90-08213						

G110 CONTROL & DATA LOOPS				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 2 OF 4
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
00006	11/72	F	E		R123 is a 390 ohm 1/4W 5% resistor R123 is the closest resistor to BS1				N11						
00007	09/72	E1	C		4 - Standoffs <u>screwed on</u>				N11						
00008	10/72	E2	C		C47 is a .01 uf 100V 20% disc capacitor C47 is directly below E40 E40 is the 1st I.C. from CT1 DO NOT COUNT PULSE TRANSFORMER AS I.C.				N/A						
C 00009	12/72	E3	C	.5	Four #18 gauge black ground jumpers on SIDE ONE INSTEAD OF ON SIDE # TWO				17-00024 (#18 black & white teflon coated)						
C 00010 & 10A	11/72	E4	C	1.0	Jumper E15-10 to E28-13 E15 is the 4th I.C. from AV1. E28 is the 6th I.C. from BE1.			1	19-05547	DZQKB					
00011	12/72				<u>NOTE:</u> This ECO deleted				N/A						
D 00012	12/72	E5	C	N/A	<u>NOTE:</u> Print update affecting only "C" etch modules.				N11						

G110 CONTROL & DATA LOOPS			ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 3 OF 4
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY.	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CB NAME
D 00013 & 13A	01/73	E6	C	.5	NOTE: Rework only "C" etch modules Jumper pin 4 to 13 on spare I.C. slot above E40 E40 is the 1st I.C. from CT1				N11	DZQMB				
00014	03/73	K	F		NOTE: This ECO affects only CS "F" etch "E" modules Jumper E15-10 to E28-13 E15 is the 4th I.C, from AV1 E28 is the 6th I.C. from BE1				N/A					
00014A	03/73	K	F		NOTE: This ECO affects E & F etch revs modules DL3 is 125 n sec. delay line with P/N 1-322-1 and or 1611327 DL3 is small delay line right of the big delay line				N/A					
C 00015 & 15A	05/73	E7	C	1.0	NOTE: This ECO affects "C" etch rev modules DL3 is 125 n sec. delay line with P/N L-00-01 and/or 1611327 DL3 is small delay line right of the big delay line			1	16-11327	DZMMG DZQKB DZQGA				
C 00016	06/73	E8	C	2.0	NOTE: Rework only "C" etch rev modules Jumper E04-04 to E07-07				N11	DZMMG DZQKB DZQGA				
00017	12/73	L	F		NOTE: This ECO affect only "E" & "F" etch rev modules Jumper E04-04 to E07-07				N11					

CONTROL & DATA LOOP				ETCH	OPTION	OPTION SERIAL#	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 4 OF 4
G110															
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO	QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME			
B 00018	10/73	E9	C	1.0	NOTE: Rework etch "C" Rev White wire of twisted pair from E32-06 feed through to E58-14 E32 is the 4th I.C from BS1 E58 is the 1st I.C from FC1	1	10-01610								
C 00019	12/73	E1C	C	1.0	NOTE: Rework "C" etch rev Visual check of jumper or etch run from E26-08 to DL1 tap 10 (Do Not Use Meter) E26 is the 4th I.C from BE1 DL1 is the biggest delay line		NIL	DZQMB							
00020 &A	01/74	M	H		NOTE: Affects "F" etch rev Visual check of jumper or etch run from E26-08 to DL1 tap 10 (Do Not Use Meter) E26 is the 4th I.C from BE1 DL1 is the biggest delay line		N/A								
00021	07/74	N N E11 E11	H F E C		NOTE: Phase in DEC 8640's to replace DEC 380's		N/A								
00022	09/76	P	H		NOTE: DEC 7438 allowable I.C. substitution for 74H01-1 at E5, E18-E22		NIL								

H15

G231 MEMORY DRIVER				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE 1 OF 3
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
B 00001	6/72	C	C	3.0	Two standoffs to prevent shorting			2	90-06892						
00002	8/72	D	D		Four standoffs on module				Nil						
D 00003	8/72	E	D	4.0	NOTE: Rework only "C" etch modules D116 is a D672 diode instead of being a resistor D116 is the only diode right of E1			16	11-05275	DZMMI					
00004 & 4A	8/72	F	E		E2 is a DEC I.C. 1074H00 E2 is the I.C closest to the top left corner.				Nil						
A 00005	8/72	E1	C	4.0	NOTE: Rework only G231's with etch rev "C" which are in 11/05 and ME11 systems. 11/45 memories do <u>not</u> need this ECO Jumper from R101 to Q7 R101 is the 3rd resistor from bottom left corner Q7 is the biggest transistor from E1				Nil						
00006	8/72	E2	C		R170 is a 100 ohm 1/4W 5% resistor R170 is the 2nd resistor from top edge of board in the 1st row of resistors left of E1				Nil						
00007	9/72	E3	C		NOTE: Print update				Nil						

215

3231 MEMORY DRIVER				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 2 OF 3
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
00008	9/72	E1A E2A E3A	C C C		C52 is a 470 pfd 100V 5% capacitor C52 is at the far left of DR1 and the only component between two transistors				Nil						
00009	12/12	E4	C	N/A	NOTE: Field service clarification for etch "C" modules				Nil						
00010	3/73	H	E		E1 is a DEC I.C. 4011 quad transistor				N/A						
00011	4/73	E5	C		E1 is a DEC I.C. 4011 quad transistor				N/A						
00012	4/73	J	E		NOTE: Affects etch "E" rev only R176 is a 4.7K 1/4W 5% resistor R176 is the 1st resistor below two transistors at the far left of EJ1				N/A						
00013	11/73	K	E		NOTE: I.C. substitution cancelled by ECO # 16				N/A						
00014	2/74	L	E		Q12 as snap-on heat sink Q12 is closest transistor to bottom left corner.				N/A						
00015	6/74	M	E ALL		NOTE: This ECO affects all etch rev modules. J1 & J2 have insulated jumper wire J1 & J2 are between E31 and E34 E31 is the last I.C. from CD slot				N/A						
00016	/74	N E6	E C		NOTE: I.C. 380 and 7380 are unsuitable E9, E15, E16, E17 are I.C. DEC 8640's E9 is the last I.C. from AV1 E15 is the 1st I.C. from BF1				N/A						

JIS

G231 MEMORY DRIVER				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 3 OF 3
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO			QTY.	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	EE NAME	
00017	01/75	P	E		Q6 is a DEC 6534C transistor Q6 is the <u>last</u> transistor from EJ1				N/A						
00018	04/75	R	E		<u>NOTE:</u> Phase in jumper wire For current loops using teflon insulated wire				N/A						

H214 - 8K x 16 BIT MEMORY STACK		ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS UNIT	SLOT	IPB	PAGE 1 OF 1
---------------------------------	--	------	--------	-----------------	-----	-----------------	----------	-----	-----	----------	------	-----	-------------

ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO	QTY	PARTS REQUIRED	MANUECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL	DATE INSTALLED	CS
00001	6/72	B			<u>NOTE:</u> Print change		Nil					
00002	1/73	C			<u>NOTE:</u> Reference chart for H214, H215, H216 and G645 etch & CS revs		Nil					
00003	6/73	D			<u>NOTE:</u> Allowable I.C. substitution is DEC 2501 to DEC 2501-01, 2501-02, 2501-03		N/A					
00004	10/73	E			<u>NOTE:</u> Print correction		Nil					
00005	11/73	F			<u>NOTE:</u> Print correction		Nil					
00006	07/74	H			<u>NOTE:</u> Documentation update		Nil					
00007 52	12/74	J			<u>NOTE:</u> DOCUMENTATION FOR AMPLE STACK		Nil					

CK

MM11-U/UP

FCR

**MM11-U
16K CORE MEMORY/PARITY
FCO Cross Reference**

**A Chronological Listing of Field Retrofit FCO's Which Must Be
Considered in the Field Installation and Maintenance of This Option/Module/Power Supply**

• Indicates FCO Conjunction Must Be Considered With Prior FCO

1 G235-80009 SEP 78
QUICK SYNOPSIS
Marginal memory under conditions of high
drive current
QUICK CHECK
750 ohm resistor at + symbol near large etch
NEW REVISION
Rework etch D to CS N

REC'D
COMMUNICATIONS SECTION

APRIL/77

NOTE: 1) MM11-U/UP are combined together for convenience

MM11-U/UP PARTS BREAKDOWN

G114	- 16K sense memory
G235	- 16K X-Y driver
H217-C	- parity memory stack (16K X 18 bit)
H217-D	- memory stack (16K X 16 bit)
M8239	- 16K timing module
MM11-U/UP	- 16K Core Memory/Parity

MM11-U/UP FIELD CODED ECO's

G114	- 15
G235	- 59

MM11-U/UP ECO PARTS

<u>NAME</u>	<u>ECO#</u>	<u>QTY</u>	<u>PART NUMBER</u>	<u>COMMENTS & DESCRIPTION</u>
G235	09	1	13-05281-00	RESISTOR

G114 16K SENSE INHIBIT		ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 1 OF 1
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO		QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME
C0001	10/73	B	B		<u>NOTE:</u> Cancelled By ECO# 1A			NIL					
00001A	10/73	B	B		Gnd Jumper from FT1 and along the bottom of the board		A/R	91-07470-00					
00002	11/73	C	B		R108 is a <u>56 OHM</u> , 1/2W, 5% resistor R108 to the right of T103 T103 is a transformer along AC1 near handle side.			N/A					
00003	10/74	D	C		<u>NOTE:</u> New Etch Rev.			NIL					
00004	04/75	E	C		<u>NOTE:</u> Part substitution due to shortage			N/A					
I 00005	05/75	F	C	.5	<u>NOTE:</u> Affects only etch "C" rev's Measure open circuit from the top left metal handle to ground			NIL					

G235 16K X-Y DRIVER		ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 1 OF 2
			MF11-1										
ECO	RELEASE DATE	CS	LTCn WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO	QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
00001	07/73	D	D		R35 is a 3.16K, 1/8W, 1% resistor R35 is located below W4 W4 is left of E2-01 E2 is the 2nd I.C. from AT1	1 1	13-00229 13-03045						
00002	09/73	E	D		R92 is NOT a 330ohm, 1/2W, 5% resistor R92 is the 4th component above R101 R101 is 220 ohm, 2W resistor left at AT1	1 2 1	11-03441 13-00271 13-02379						
00003	11/73	F	D		R29 is a 120K, 1/2W 5% resistor R29 is the 1st resistor above Q14 Q14 is the transistor above E4 E4 is the 2nd I.C. from BL1		N/A						
00004	01/74	H	D		D2, D3, D4 are deleted No diodes between E2 and R18 R18 is a 100ohm resistor, above E2	1 1	15-05321 19-10466						
00005	04/74	J	D		C47 is a .022 ufd capacitor C47 is the 1st capacitor below T2 T2 is a transformer at the far left of AN1	2 1	10-11683 13-04855						
00006	08/74	K	D		Delete C44 Only one 47ufd, 20V, 10% capacitor still present (not two) between Q12 and Q13 Q12 and Q13 are the 1st and 2nd transistors from AE1		NIL						

G235 16K X-Y DRIVER		ETCH	OPTION	OPTION SERIAL#	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 2 OF 2
ECO	RELEASE DATE	CS	ETCH WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO		QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME
00007	04/75	L	D		NOTE: Parts substitution due to shortages			NIL					
I 00008	06/75	L	D		NOTE: Must have if used on MA20-M for PDP10 R23 is an 1K 1/2W resistor R23 is the only resistor left of AAl		1 1	13-00364 13-02388					
I 00009 8A	06/76	N	J		R103 is a 75 ohm 1W 5% resistor R103 is immediately right of Q12 Q12 is the 2nd transistor from AC1								

H217 16K STACK		ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAD	BOX	SYS. UNIT	SLOT	IPB	PAGE 1 OF 1	
ECO	RELEASE DATE	CS	FROM WL	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO		QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATED	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME	
00001	05/74				NOTE: Manufacturing Change			NIL						
00002	07/74				NOTE: Document Change			NIL						
00003	10/74	B	E		NOTE: Rework H217-B and C (18 or 19 Bit) Diodes D29, D30 are deleted D29, D30 were Diodes left of CE1 but right of the resistor network			NIL						
00004	03/76	C	E		NOTE: Manufacturing change.			NIL						

16K UNIBUS TIMING				ETCH	OPTION	OPTION SERIAL #	PDP	SYSTEM SERIAL #	LOCATION	CAB	BOX	SYS. UNIT	SLOT	IPB	PAGE 1 OF 1
M8293					MF11-U										
ECO	RELEASE DATE	CS	ETCH WI	ECO HRS. TIME	QUICK CHECK CAUTION - NOT COMPLETE ECO	QTY	PARTS REQUIRED	MAINDECS REQUIRED	PRINT SET UPDATE	ACTUAL INSTALL TIME	DATE INSTALLED	CE NAME			
00001	10/73	B	B		NOTE: This is a mandatory ECO Measure continuity from E21-03 to E25-13 L21 is the 2nd I.C. from CL1 E25 is below E21		NIL								
000J2	11/73	C	B		NOTE: This is a mandatory ECO Measure continuity from E03-05 to DL3-05 DL3 is the only delay line left of AR1		NIL								
000J3 &A	06/74	D	C		NOTE: New etch rev		N/A								
00004	06/75	E	C		NOTE: Phase in DEC 8640 to replace DEC 380		N/A								
00005	06/76	F	C B		NOTE: Introduces M8293-YB for XM15 M8293-YB can be distinguished by checking for jumper from E38-12 to E38-13 E38 is the 4th I.C. from DT1		NIL								